

## Inside Technologies Permissive Change II

The difference is: The new cable is without a shield and 2 ferrites EM2 and EM3 were replaced by 0 ohm resistor. But schematics, block diagram, manual, etc. didn't change, it's exactly same a last one.