

Response to E04-000089-2

- 1-3. A revised manual has been uploaded.
4. The equipment code should be DXT. Please change the 731 form to reflect this.