



# ROGERS LABS, INC.

4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone / Fax (913) 837-3214

December 4, 2006

Timco Engineering Inc.  
849 NW State Road 45  
Newberry, FL 32669

Federal Communications Commission  
Equipment Approval Services  
P.O. Box 35815  
Pittsburgh, PA 15251-3315

Applicant: SPEEDCAM INC.  
1755 Lexington Avenue  
Deland, FL 32724

Equipment: FCC ID: Q4X-HHTU1  
FCC Rules: Part 90 LMR UHF Transceiver

Gentlemen:

SpeedCam Inc. requests acceptance of the labeling proposal described below for transceivers bearing FCC identifier Q4X-HHTU1. The subject transceivers are compact handheld models as shown in the picture below. This equipment must be assembled by the end user before use and is shipped without the battery attached. This configuration exposes the FCC ID label information to the end user whenever the battery is removed.

Because the majority of the transceiver housing is composed of display, speaker, operating controls, and a removable battery pack, there is extremely limited space available to attach the required label carrying the FCC identifier. Attaching the label to the battery pack is not acceptable because the battery pack is a removable item. For this reason, SpeedCam Inc. proposes placing the label carrying the FCC identifier on the case below the removable battery.

In this location, the label will be protected from physical abuse and remain readable for the anticipated life of the device. The packaging for this equipment allows the transceiver for the equipment and FCC ID label information to be viewed at the time of purchase upon opening the packaging and removing the transmitter.

ROGERS LABS, INC.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214

Speedcam, Inc.  
MODEL: MT16U  
Test #: 060515U  
Test to: FCC Parts 2 and 90

IC: 6725A-HHTU1  
FCCID#: Q4X-HHTU1  
Page 1 of 2  
MT16U FCC ID Label request 12/4/2006



"This device must be restricted to occupational use to satisfy FCC RF exposure compliance. See the owner's manual for specific operating requirements."

**SPEEDCOM**  
COMMUNICATIONS

**FCC ID: Q4X-HHTU1**

**IC: 6725A-HHTU1**

**CE NO. 0681**

This device complies with part 15 of the FCC rules. Operation is subject to the condition that this device does not cause harmful interference.

**SER # 0000000000**

UHF Transceiver      Made in China

ROGERS LABS, INC.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214

Speedcam, Inc.  
MODEL: MT16U  
Test #: 060515U  
Test to: FCC Parts 2 and 90

IC: 6725A-HHTU1  
FCCID#: Q4X-HHTU1  
Page 2 of 2  
MT16U FCC ID Label request 12/4/2006