

A Covering Letter requesting the new FCC id

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Attention: Application Examiner/ Review Engineer

Subject: Request changes to the FCC id per section 2.933 of FCC rules

Reference: FCC ID: Q78-MF193

To The Commission:

This ID modification request applies to the FCC ID: Q78MF193 issued on 08/23/2011. There is a type error in the original application form of FCC ID, i.e., the FCC ID should be Q78-MF193 (right ID) but not Q78MF193 (wrong ID). Note that in all other uploaded files, such as reports, photos and labels etc, the right ID is used except application form. Due to this error, the wrong FCC ID: Q78MF193 became to the final FCC identification.


1. This modification does not correlate to any product's schematic, BOM and the equipment is identical.
2. The original test results are applicable and representative of this changed device
3. External photographs are included in this application.
4. FCC ID label format is included in this application.

Sincerely,

ZTE Corporation

Product Certification Director

Royce Wang



2012/6/28