



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

June 3, 2004

RE: SendFar Technolgy Co. Ltd.

FCC ID: QA5-MPI-04001

After a review of the submitted information, I have a few comments on the above referenced Application.

Administrative Issues:

- 1) FYI...(For Your Information – No Response Necessary). The modular approval letter does reference the correct FCC ID, and internal components list. However, the manufacture name in the letter appears incorrect.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.