
from **September Radecki** <september.radecki@ccsemc.com>

[hide details](#) Nov 5 (21 hours ago) 

to "Timothy M. Dwyer" <tim.dwyer@ccsemc.com>

cc Thu Chan <thu.chan@ccsemc.com>

date Nov 5, 2007 6:47 PM

subject RE: Broadcom Corporation, FCC ID: QDS-BRCM1022, Assessment NO.: AN07T7202 and AN07T7203, Notice#1

Reply

Hi Tim,

Below are the answers to your questions on the above application:

- Q1. The user manual does not contain RF exposure information. Please revise the user manual.
<CCS ANSWER:> Please see attached page to be inserted into the final manual.
- Q2. The user manual does not include a statement advising that use of 5.15-5.25 GHz is limited to indoor operation only. Please revise the user manual.
<CCS ANSWER:> Please see attached page to be inserted into the final manual.
- Q3. Pages 150-155 include instructions for removal and installation of the device. This is in conflict with the grant conditions. Please revise the user manual.
<CCS ANSWER:> The user manual is not revised for this item, however, a bios lock document has been provided which addresses this problem. The bios lock document is to be considered confidential, and a Request for Confidentiality is provided here as well as the bios lock document.

Thanks and best regards,
September

September Radecki
Compliance Certification Services
47173 Benicia Street
Fremont, CA 94538
phone: 1-510-771-1090
fax: 1-510-661-0888
September.Radecki@CCSEMC.com <mailto:September.Radecki@CCSEMC.com>

-----Original Message-----
From: Timothy M. Dwyer
Sent: Monday, September 17, 2007 6:02 PM
To: September Radecki
Cc: Timothy M. Dwyer; Thu Chan
Subject: Broadcom Corporation, FCC ID: QDS-BRCM1022, Assessment NO.: AN07T7202 and AN07T7203, Notice#1

Hello September,

I am sending this directly to you (cc: Thu) as I believe all items are ones that you will handle.

This notice is combined with AN07T7202 as all items relate to the user manual used for both applications. A separate notice for AN07T7203 will not be sent. The reply to this notice will be used for both applications.




- Q1. The user manual does not contain RF exposure information. Please revise the user manual.
- Q2. The user manual does not include a statement advising that use of 5.15-5.25 GHz is limited to indoor operation only. Please revise the user manual.
- Q3. Pages 150-155 include instructions for removal and installation of the device. This is in conflict with the grant conditions. Please revise the user manual.

Best regards,

Tim Dwyer
CCS Technical Reviewer

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

3 attachments — [Download all attachments](#)

- **FCC Regulatory Info page for Manual.pdf**
38K [View as HTML](#) [Download](#)
- **Confidentiality Request QDS-BRCM1022.pdf**
19K [View as HTML](#) [Download](#)
- **Dell_System_ID_lock_v0.3_Theory of Operations.pdf**
135K [View as HTML](#) [Download](#)