



Corporate Headquarters

1803 Research Blvd., Suite 404, Rockville. MD 20850 USA

Tel:301.309.8500 Fax:301.309.8851

Date: February 25. 2004

To:

AirVast Technology Inc.

4F,No. 1, Ln.21, Hsin Hua Rd., Kueishan Industria Park, Taoyuan 330, Taiwan,

R.O.C.

Re: Change of Identification Authorization

FCC ID: MFM-11-136

To Whom It May Concern:

This letter grants authorization for representatives of AirVast Technology Inc. to apply to the FCC for a change in identification as specified under 47CFR2.933 of the FCC rules.

This authorization applies to Teletronics International Inc. 11Mbps WIRELESS LAN Card, FCC ID:MFM-11-136, granted on February 24. 2004. The equipment is electrically identical the only change being the labels on the device. The original test results continue to be representative of and applicable to the changed equipment.

Sincerely Yours,

By  _____

Name: Bank Lu

Asian Branch Office:

30F, No29-5. Sec 2, Chungcheng E.Rd Tamshui, Taipei Hsien 251, Taiwan,
ROC.

Tel:886-2-8809-7992

Fax:886-2-8809-7830