

Report No.: 0312718
Model No.: 3215

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement


DLT: 18.68ms

-0.03dB

RB 3MHz# AT 10dB

ALV: 97.00dBuV

VB 3MHz



Tested By: KL
(Kwok Wong)
Date: 7/8/03

Checked By: [Signature]
(Anthony Chan)
Date: 8/8/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 80ms

F: 27.145200MHz

Report No.: 0312718
Model No.: 3215

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement


PLT: 18.84ms

0.01dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: KL
(Kenneth Wong)
Date: 7/8/03

Checked By: [Signature]
(Anthony Chan)
Date: 8/8/03

Test Result: Pass / Fail / NA

DT: 0us

TS: 30ms

F: 27.145200MHz

Report No.: 0312718
Model No.: 3215

Pursuant to FCC Part 15 Section 15. 222 Emissions Requirement


PLT: 1.50ms

-0.30dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: KL
(Kerok Wong)
Date: 7/8/03

Checked By: Anthony Chen
(Anthony Chen)
Date: 8/8/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 30ms

F: 27.145200MHz

Report No.: 0312718
Model No.: 3215

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement


PLT: 180us

-0.34dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: KL
(Kenneth Wong)
Date: 7/8/03

Checked By: [Signature]
(Anthony Chan)
Date: 8/8/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 30ms

F: 27.145200MHz