

Report No.: 038641
Model No.: 3290

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

MKA 18.562 msec

REF 97.0 dB μ V

AT 10 dB


-.26 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: *Kenneth W. W.*

Date: 25/11/03

Checked By: *Anthony Chan*

Date: 27/11/03

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec

Report No.: 0318641
Model No.: 3290

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

hp

MKA 18.500 msec

REF 97.0 dB μ V

AT 10 dB

.03 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: [Signature]
(Kermit Wong)

Date: 25/11/03

Checked By: [Signature]
(Dimitry Chen)

Date: 27/11/03

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 25.0 msec

Report No.: 0318641
Model No.: 3290

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

hp

MKA 1.5620 msec

REF 97.0 dB μ V

AT 10 dB

-4.81 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: *[Signature]*
(Karnel Wong)

Date: 25/11/03

Checked By: *[Signature]*
(Romy Chou)

Date: 27/11/03

Test Result : Pass / Fail / *NA*

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 25.0 msec

Report No.: 03/8641
Model No.: 3290

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

MKA 500.00 μ sec

-4.64 dB

REF 97.0 dB μ V


AT 10 dB

PEAK

LOG

10

dB/



VA SB
SC FC
CORR

Tested By: [Signature]
(Kerrol Wong)

Date: 25/11/03

Checked By: [Signature]
(Anthony Chan)

Date: 27/11/03

Test Result: Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 25.0 msec