

## RF EXPOSURE STATEMENT

**A Narda 8616 radiation Meter with suitable probes was used and there was NO measurable radiation even at a distance of 0.5 meters from the transmitter cabinet**