



Reliability Laboratory of Huawei Technologies Co., Ltd.  
Administration Building, Headquarters of Huawei Technologies Co., Ltd., Bantian, Longgang District, Shenzhen, 518129, P.R.C  
Tel: +86 755 28780808 Fax: +86 755 89652518

---

## Declaration

To whom it may concern,

As to the product AP7110SN-GN & AP7110DN-AGN & AP5010DN-AGN & AP5010SN-GN offered by Huawei Technologies Co., Ltd., we declare that country codes of the four AP models have been fixed by the manufacturer and these APs cannot work in 40 MHz mode at the 2.4 GHz frequency band. Any user or engineering personnel cannot configure the APs to work in 40 MHz mode at the 2.4 GHz frequency band by changing country codes or any other methods.

Person responsible for making this declaration:

Signature: Li Yingzhe Date: November 27, 2012

NAME (Please print or type): Li Yingzhe

TITLE (Please print or type): Cooperation Manager

COMPANY (Please print or type): Huawei Technologies Co., Ltd.