



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

August 28, 2002

RE: New Atico Intl. Ltd.

FCC ID: QJHW58G0040

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The TX Label contains the FCC logo. This logo is used only for devices that meet with a DoC authorization (for example if the receiver was tested under a DoC authorization, then the receiver would be labeled with the FCC Logo). Please explain why the TX is subject to a DoC authorization or provide a corrected label with the FCC logo removed.
- 2) Please provide a photograph or drawing that show the placement of the label on the device.
- 3) The EUT is considered a portable device. Portable devices according to ANSI C63.4 must be tested with the EUT positioning in each of 3 axis. Please explain if this was performed. If this was not performed, please evaluate the EUT for all 3 axis and provide the worse case data.
- 4) Please provide information to show compliance with (a)(1)-(3) as appropriate. Plots should be provided showing that the normal duration of transmission over each 15 seconds.
- 5) Please confirm if the device was tested with a new battery.

A handwritten signature in black ink, appearing to read "Timothy R. Johnson".

Timothy R. Johnson  
Examining Engineer

Direct Phone: 404-414-8071  
[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.