



June 5, 2004

RE: FCC ID: QMNRH-57\_ATCB001392

**Attention:** Andreas Gillmeier

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please provide a photo of the bottom side of the board shown in photo 3 of the internal photos.  
Also, please provide photos of the back side what appears to be the keypad assembly.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.