



NOKIA, INC.
6000 Connection Drive
Irving, Texas 75039
972-894-5000

18 August, 2005

Attention: Equipment Authorization Branch

RE: FCC ID: QMNRM-66
PER: 47 CFR 2.1043

RF
--

BB
--

Mechanics
--

Other
VCTCXO underfill change (for strength) and package supplier change – drop in replacement requiring no matching component changes.

Results of internal review (FCC focus):
FCC 2.1051, 2.1053, 2.1055(a)(1)(b), 24.235, 2.1055(d)(1)(2), 24.235, 15.109, 15.111

NOKIA MOBILE PHONES

Michael Mobley
Product Certification Officer, Nokia Dallas