FCC ID: BULPA25

Part 2.995—Frequency Stability

Since the amplifier contains no internal oscillator, and since the frequency of the amplified signal will depend on the characteristics of the driver (assumed to be a type accepted transmitter whose rf power output is approximately 5 watts), this part does not apply to this application.