

Report No.: 0217467
Model No.: 2161

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement

MKA 17.250 msec

REF 117.0 dB μ V

AT 20 dB

-.03 dB

PEAK

LOG


10

dB/

VA SB

SC FC

CORR



Tested By:

(Signature)
(Cory Li)

Date: 2012-02

Checked By:

(Signature)
(Anthony Chan)

Date: 23/12/2012

Test Result : Pass / Fail / NA

CENTER 49.661 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 75.0 msec

Report No.: 0247467
Model No.: 2161

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

MKA 17.250 msec

REF 117.0 dB μ V

AT 20 dB

.02 dB

PEAK

LOG


10

dB/

VA SB

SC FC

CORR



Tested By:

Date: 20-12-02

Checked By:

Date: 23/12/2002

Test Result : Pass / Fail / NA

CENTER 49.861 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

INTERTEK TESTING SERVICES

Report No.: 0217467
Model No.: 2/61

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement

MKR 1.4250 msec

REF 117.0 dB μ V

AT 20 dB

-.12 dB

PEAK

LOG


10

dB/

VA SB

SC FC

CORR



Tested By:

(Signature)
(Gary G)

Date: 20-12-02

Checked By:

(Signature)
(Bobby G)

Date: 23/12/2002

Test Result : Pass / Fail / NA

CENTER 49.861 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

Report No.: 0217467
Model No.: 2161

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

MKA 450.00 μ sec

REF 117.0 dB μ V

AT 20 dB

-.09 dB

PEAK

LOG


10

dB/

VA SB

SC FC

CORR



Tested By:

(Signature)
(Charles C.)

Date: 20-12-02

Checked By:

(Signature)
(Anthony Chen)

Date: 27/12/2002

Test Result : Pass / Fail / NA

CENTER 49.861 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec