


INTERTEK TESTING SERVICES

Report No.: 0400934
Model No.: 2340

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

hp
REF 67.0 dBμV AT 10 dB MKR 16.362 msec
LOG 10 dB/



Tested By: *Kenneth Wong*

Date: 21/1/04

Checked By: *[Signature]*

Date: 5/2

Test Result : Pass / Fail / NA

CENTER 49.660 MHz SPAN 0 Hz
#RES BW 3.0 MHz #VBW 3 MHz #SWP 55.0 msec


INTERTEK TESTING SERVICES

Report No.: 0400934
Model No.: 2340

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

REF 87.0 dB μ V AT 10 dB MKR 16.375 msec
.45 dB

PEAK
LOG
10
dB/



VA SB
SC FC
CORR

Tested By: *[Signature]*
(*Carroll Wong*)

Date: 2/11/04

Checked By: *[Signature]*
(*[Signature]*)

Date: 8/2

Test Result: Pass / Fail / NA

CENTER 49.860 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz
#SWP 25.0 msec

Code: bandwidth plot_a / Effective Date: 15 Jul 2002

INTERTEK TESTING SERVICES

Report No.: 0400934
Model No.: 2340

Pursuant to FCC Part 15 Section 15.231 Emissions Requirement

typ

MKA 1.3750 msec

REF 87.0 dB μ V

AT 10 dB

.42 dB

PEAK

LOG


10

dB/

VA SB

SC FC

CORR



Tested By: LK
(Kenneth Wong)

Date: 21/1/04

Checked By: [Signature]
(100%)

Date: 5/2

Test Result: Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 25.0 msec

Code: bandwidth plot_a / Effective Date: 15 Jul 2002


INTERTEK TESTING SERVICES

Report No.: 0400934
Model No.: 2340

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

for MKR 500.00 μ sec
REF 67.0 dB μ V AT 10 dB 1.69 dB

PEAK
LOG
10
dB/



VA SB
SC FC
CORR

Tested By: *[Signature]*
(Kerrel Woy)

Date: 21/1/04

Checked By: *[Signature]*
(Kerrel Woy)

Date: 5/2

Test Result : Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 25.0 msec
Code: bncvithplot_a / Effective Date: 15 Jul 2002