

Report No.: 0309071
Model No.: 2350Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


DLT: 19.60ms

0.07dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 50ms

F: 49.850000MHz

Tested By: LT
(Kenneth Wong)
Date: 10/6/03Checked By: [Signature]
(Anthony Chan)
Date: 12/6/03Test Result : Pass / Fail / NA

Report No.: 0309071
Model No.: 2350

Pursuant to FCC Part 15 Section 15.225 Emissions Requirement


PLT: 19.68ms

0.06dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 30ms

F: 49.860000MHz

Tested By: LR
(Vernik Wong)
Date: 10/6/03Checked By: [Signature]
(Anthony Chan)
Date: 12/6/03Test Result : Pass / Fail / NA

Report No.: 0309071
Model No.: 2350Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


PLT: 780us

-0.05dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 30ms

F: 49.850000MHz

Tested By: KL
(Kenneth Wong)
Date: 10/6/03Checked By: [Signature]
(Anthony Chen)
Date: 12/6/03Test Result: Pass / Fail / NA

Report No.: 0307071
Model No.: 2350

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


PLT: 240us

-0.06dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: [Signature]
(Kevin Wang)
Date: 10/6/03

Checked By: [Signature]
(Anthony Chan)
Date: 12/6/03

Test Result : Pass / Fail / NA

DT: 0us

TS: 30ms

F: 49.860000MHz