

INTERTEK TESTING SERVICES

Report No.: 0415321
Model No.: #2490

hp

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement MKB 10.750 msec

REF .0 dBm

AT 10 dB

.00 dB

PEAK

LOG


10

dB/

WA SB

SC LS

CORR



Tested By: KA
(Kenneth Wong)

Date: 12/8/04

Checked By: [Signature]
()

Date: 12/8

Test Result : Pass / Fail ☒ NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 50.0 msec

INTERTEK TESTING SERVICES

Report No.: 0415321
Model No.: #2490

hp

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement MKP 10.837 msec

REF .0 dBm

AT 10 dB

.02 dB

PEAK

LOG


10

dB/

WA SB

SC LS

CORR



Tested By: K
(Kenneth Wong)

Date: 12/8/04

Checked By: [Signature]
([Signature])

Date: 12/8/04

Test Result: Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 15.0 msec

INTERTEK TESTING SERVICES

Report No.: 0415321
Model No.: #2440

hp

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement MKR 900.00 μ sec

REF .0 dBm

AT 10 dB

-.73 dB

PEAK

LOG


10

dB/

WA SB

SC LS

CORR



Tested By: KA
(Kenneth Wong)

Date: 12/8/04

Checked By: Ivan Wong

Date: 12/8

Test Result : Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 15.0 msec

INTERTEK TESTING SERVICES

Report No.: 044521
Model No.: #2490

hp

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement 300.00 μ sec

REF .0 dBm

AT 10 dB

-.77 dB

PEAK

LOG


10

dB/

WA SB

SC LS

CORR



Tested By: KW
(Kenneth Wong)

Date: 12/8/04

Checked By: [Signature]
(Ivan Wong)

Date: 12/8

Test Result: Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 15.0 msec