


Appendix 1



Test Results

Carrier Frequency Separation




Date: 30.JAN.2012 09:19:30


Number of hopping channels



Dwell Time



Date: 30.JAN.2012 09:32:55




Date: 30.JAN.2012 09:34:24

20dB Bandwidth


Modulation: GFSK

Tx frequency: 2402MHz




Modulation: GFSK

Tx frequency: 2441MHz




Modulation: GFSK
Tx frequency: 2480MHz




Date: 30.JAN.2012 09:41:37

Modulation: 8DPSK
Tx frequency: 2402MHz




Date: 30.JAN.2012 09:46:50

Modulation: 8DPSK
Tx frequency: 2441MHz



Date: 30.JAN.2012 09:45:40

Modulation: 8DPSK
Tx frequency: 2480MHz




Date: 30.JAN.2012 09:44:14

Peak Output Power


Modulation: GFSK

Tx frequency: 2402MHz




Modulation: GFSK

Tx frequency: 2441MHz




Modulation: GFSK
Tx frequency: 2480MHz




Date: 30.JAN.2012 09:57:03

Modulation: Pi/4 DQPSK
Tx frequency: 2402MHz




Date: 30.JAN.2012 09:53:20

Modulation: Pi/4 DQPSK
Tx frequency: 2441MHz




Date: 30.JAN.2012 09:52:22

Modulation: Pi/4 DQPSK
Tx frequency: 2480MHz




Date: 30.JAN.2012 09:51:28

Modulation: 8DPSK
Tx frequency: 2402MHz




Date: 30.JAN.2012 09:48:09

Modulation: 8DPSK
Tx frequency: 2441MHz



Date: 30.JAN.2012 09:49:05


Modulation: 8DPSK
Tx frequency: 2480MHz



Date: 30.JAN.2012 09:50:27


Band Edge Compliance

Tx frequency: 2402MHz (conducted measurement; hopping on)




Date: 30.JAN.2012 10:04:14

Tx frequency: 2480MHz (conducted measurement; hopping on)




Date: 30.JAN.2012 10:02:23

Tx frequency: 2402MHz (conducted measurement; hopping off)




Date: 30.JAN.2012 10:06:53

Tx frequency: 2480MHz (conducted measurement; hopping off)




Date: 30.JAN.2012 10:08:14

Tx frequency: 2402MHz (radiated measurement)




BABARCODA / BT BARCODE READER / BOK-L / 00120110119-001 / 24
02MHz / VERT
Date: 13.JAN.2012 15:48:28



BARCODE READER / VERT/ 2402


Date: 17.JAN.2012 17:17:07



BABARCODA / BT BARCODE READER / BOK-L / 00120110119-001 / 24

02MHz / HORI


Date: 13.JAN.2012 15:47:22



BARCODE READER / HORI / 2402

Date: 17.JAN.2012 17:15:59


Tx frequency: 2480MHz (radiated measurement)



BABARCODA / BT BARCODE READER / BOK-L / 00120110119-001 / 24


80MHz / VERT

Date: 13.JAN.2012 15:42:04



BARCODE READER / VERT / 2480


Date: 17.JAN.2012 17:10:09



BABARCODA / BT BARCODE READER / BOK-L / 00120110119-001 / 24

80MHz / HORI

Date: 13.JAN.2012 15:43:28




BARCODE READER / HORI / 2480

Date: 17.JAN.2012 17:11:04


Spurious Emissions - Conducted

Tx frequency: 2402MHz




Date: 30.JAN.2012 10:21:47

Tx frequency: 2441MHz



Date: 30.JAN.2012 10:18:49

Tx frequency: 2480MHz



Date: 30.JAN.2012 10:15:47