

Change in Identification

PHOENIX TESTLAB GmbH
Product Certification
Königswinkel 10

D 32825 Blomberg

Date: May 28, 2010

Bluetooth Module / FCC ID ED9LMX9838

Dear Sir or Madam,

we apply for change in identification for the grant issued under FCC ID ED9LMX9838.

The original grant is dated 02/08/2007.

The reason of change is the co-location of a RFID reader (13.56 MHz).

Thank you for your attention in this matter.

Fred Weiber
Signature *FRED WEBER*

National Semiconductor Corporation
2900 Semiconductor Drive
P.O. Box 58090
Santa Clara, CA 95052-8090