

Scott McCutchan

To: kyle@celectronics.com
Subject: FCC ID: QTE1000

Mr. Fujimoto,

In order for processing of this application (FCC ID: QTE1000) to continue, the following issue(s) will have to be addressed:

- 1) The data sheets in the test report show that the fundamental emission was averaged. For transmitters operating under section 15.249, the quasi-peak value of the fundamental must comply with the limit.
- 2) The FCC label may not be placed on the battery cover. Please submit a new diagram showing the location of the label. It must be visible at the time of purchase.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted.

Please upload your response to our electronic filing website using a correspondance number of "QTE1000-1".

If you have any questions, feel free to contact me.

Best regards,

Scott McCutchan
Operations Manager
Compatible Electronics TCB
(714) 579-1489
fax (714) 579-1850
<http://www.celectronics.com>

Correspondence by Project

Project Number:

1018476423

Correspondence Number	Memo
QTE1000-1	<p>1) The data sheets in the test report show that the fundamental emission was averaged. For transmitters operating under section 15.249, the quasi-peak value of the fundamental must comply with the limit.</p> <p>Response: The data sheet for the fundamental should of said "QP" instead of "A". The test report has been revised to show the change in the data sheet. Please see the attachment for revised test report.</p> <p>2) The FCC label may not be placed on the battery cover. Please submit a new diagram showing the location of the label. It must be visible at the time of purchase.</p> <p>Response: The FCC label drawing has been revised so that the label is on the left hand side of the unit, next to the belt clip. Please see the attachment for revised FCC ID Label.</p>