

Project Number: 08CA45713
Model Number: 240-030-970

File Number MC15562


Test Report No: 08CA45713-FCC
Date of Issue: September 24, 2008

INTERNAL PHOTOS

Inside 1



Inside 2



Project Number:
Model Number:



08CA45713
240-030-970

File Number

MC15562

Test Report No: 08CA45713-FCC
Date of Issue: September 24, 2008

Main Board



Project Number:
Model Number:


08CA45713
240-030-970

File Number

MC15562

Test Report No: 08CA45713-FCC
Date of Issue: September 24, 2008

LCD Panel



Project Number:
Model Number:



08CA45713
240-030-970

File Number

MC15562

Test Report No: 08CA45713-FCC
Date of Issue: September 24, 2008

Power Switch Board



Project Number:
Model Number:



08CA45713
240-030-970

File Number

MC15562

Test Report No: 08CA45713-FCC
Date of Issue: September 24, 2008

Receptacle Board



Project Number:
Model Number:


08CA45713
240-030-970

File Number

MC15562

Test Report No: 08CA45713-FCC
Date of Issue: September 24, 2008

Rotary switch Board



Project Number:
Model Number:



08CA45713
240-030-970

File Number

MC15562

Test Report No: 08CA45713-FCC
Date of Issue: September 24, 2008

RS 232 Board



Project Number:
Model Number:



08CA45713
240-030-970

File Number



MC15562

Test Report No: 08CA45713-FCC
Date of Issue: September 24, 2008

SDI Board



Sensor Board



Project Number:
Model Number:



08CA45713
240-030-970

File Number

MC15562

Test Report No: 08CA45713-FCC
Date of Issue: September 24, 2008

Temp sensor Board



Project Number:
Model Number:


08CA45713
240-030-970

File Number

MC15562

Test Report No: 08CA45713-FCC
Date of Issue: September 24, 2008

Wireless rx Board



Project Number:
Model Number:

08CA45713
240-030-970

File Number

MC15562

Test Report No: 08CA45713-FCC
Date of Issue: September 24, 2008

Wireless rx SUB Board

