

# **TIMCO** ENGINEERING INC.

849 NW State Road 45

Newberry, Florida 32669

<http://www.timcoengr.com>

888.472.2424 F 352.472.2030 email: [tei@timcoengr.com](mailto:tei@timcoengr.com)

March 24, 2003

FCC

SUBJECT: ZHONGSHAN TIANPENG ELECT.LIGHT.AND COMM.EQUIP.FACT -  
FCC ID: QXGSREEUT

REFERENCE: JOB 375HC3

To whom it may concern:

The conducted emission plots for this job appear to be over limit. The Table of conducted emissions is within limits. The submitting laboratory was questioned regarding the differences. The difference was a result of making "peak" measurements in the plots versus "quasi-peak" measurements in the tabulated data. Their written response follows:

Dear Sir,

Please see attached information.

The test result curve was measured by peak detector, & test final data was measured by Quasi-Peak detector.

B/RGDs

J.K. Hsu

Wise Team Technical Services Co.

e-mail: [info@wise-team.com](mailto:info@wise-team.com)

Very truly yours,  
Frank (for)

Sid Sanders