

Response to TCB Findings

The Class II PC does not allow change of power or field strength ratings (2.1043a)). The permissive change letter and the test report mentions lowering of output power to compensate for the higher gain antenna. Please clarify.

Response: The field strength rating and EIRP of this device has not changed. Yes, the output power at the connector was reduced to facilitate a higher gain antenna, but the measured field strength is almost identical to the original application.