

# INTERTEK TESTING SERVICE

Report No: HK11040039-1

## Configuration Photographs

### Worst-Case Radiated Emissions

(Front View)

Model: 886350



# INTERTEK TESTING SERVICE

Report No: HK11040039-1

## Configuration Photographs

### Worst-Case Radiated Emissions

(Rear View)

Model: 886350

