

Report No.: 06007831
Talk (1 Handset) Mode

Tested By: Hong, Report No.: 06007831

Scan Settings (1 Range)

----- Frequencies -----			Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

0.29500	33.4	60.3
---------	------	------

Frequency	AV Level	AV Limit
MHz	dBuV	dBuV

no Results

* limit exceeded