



Tested By:Hong, Report No.:03180671

Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF 60dB


Final Measurement: x QP / + AV

Transducer No.	Start	Stop	Name
22	9k	30M	EW0699

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB



Report No.: 03180671
Talk (1 Handset) Mode

Tested By:Hong, Report No.:03180671

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency QP Level QP Limit

MHz dBuV dBuV

0.22000 35.8 62.9

0.32000 34.3 59.7

0.41500 32.6 57.6

Frequency AV Level AV Limit

MHz dBuV dBuV

no Results

* limit exceeded