







11N20SISO_Ant1_2462_1000~3000




11N20SISO_Ant1_2462_3000~5000




11N20SISO_Ant1_2462_5000~7000




11N20SISO_Ant1_2462_7000~9000




11N20SISO_Ant1_2462_9000~11000




11N20SISO_Ant1_2462_11000~13000




11N20SISO_Ant1_2462_13000~15000




11N20SISO_Ant1_2462_15000~17000




11N20SISO_Ant1_2462_17000~19000




11N20SISO_Ant1_2462_19000~21000




11N20SISO_Ant1_2462_21000~23000




11N20SISO_Ant1_2462_23000~25000




11N40SISO_Ant1_2422_30~1000




11N40SISO_Ant1_2422_1000~3000




11N40SISO_Ant1_2422_3000~5000




11N40SISO_Ant1_2422_5000~7000




11N40SISO_Ant1_2422_7000~9000




11N40SISO_Ant1_2422_9000~11000




11N40SISO_Ant1_2422_11000~13000




11N40SISO_Ant1_2422_13000~15000




11N40SISO_Ant1_2422_15000~17000




11N40SISO_Ant1_2422_17000~19000




11N40SISO_Ant1_2422_19000~21000




11N40SISO_Ant1_2422_21000~23000




11N40SISO_Ant1_2422_23000~25000




11N40SISO_Ant1_2437_30~1000




11N40SISO_Ant1_2437_1000~3000




11N40SISO_Ant1_2437_3000~5000




11N40SISO_Ant1_2437_5000~7000




11N40SISO_Ant1_2437_7000~9000




11N40SISO_Ant1_2437_9000~11000




11N40SISO_Ant1_2437_11000~13000




11N40SISO_Ant1_2437_13000~15000




11N40SISO_Ant1_2437_15000~17000




11N40SISO_Ant1_2437_17000~19000




11N40SISO_Ant1_2437_19000~21000




11N40SISO_Ant1_2437_21000~23000




11N40SISO_Ant1_2437_23000~25000




11N40SISO_Ant1_2452_30~1000




11N40SISO_Ant1_2452_1000~3000




11N40SISO_Ant1_2452_3000~5000




11N40SISO_Ant1_2452_5000~7000




11N40SISO_Ant1_2452_7000~9000




11N40SISO_Ant1_2452_9000~11000




11N40SISO_Ant1_2452_11000~13000




11N40SISO_Ant1_2452_13000~15000




11N40SISO_Ant1_2452_15000~17000




11N40SISO_Ant1_2452_17000~19000




11N40SISO_Ant1_2452_19000~21000



11N40SISO_Ant1_2452_21000~23000



11N40SISO_Ant1_2452_23000~25000




Appendix G: Duty Cycle


TestMode	Antenna	Frequency[MHz]	Transmission Duration [ms]	Transmission Period [ms]	Duty Cycle [%]	Factor
11B	Ant1	2412	12.42	12.54	99.04	0.04
		2437	12.42	12.54	99.04	0.04
		2462	12.42	12.55	98.96	0.05
11G	Ant1	2412	2.06	2.10	98.10	0.08
		2437	2.06	2.10	98.10	0.08
11N20SISO	Ant1	2412	1.92	1.96	97.96	0.09
		2437	1.92	1.96	97.96	0.09
		2462	1.92	1.96	97.96	0.09
11N40SISO	Ant1	2422	0.94	0.99	94.95	0.23
		2437	0.94	0.99	94.95	0.23
		2452	0.94	0.99	94.95	0.23

Note : We have evaluated SISO, MIMO mode, shown in the report is the worst data..


11B_Ant1_2412




11B Ant1 2437




11B Ant1 2462




11G_Ant1_2412




11G_Ant1_2437




11N20SISO_Ant1_2412




11N20SISO_Ant1_2437




11N20SISO_Ant1_2462



11N40SISO_Ant1_2422



11N40SISO_Ant1_2437



11N40SISO_Ant1_2452

