

(New addition iron shell)
For ESY10I1E, Built-in PoE






Cerpass Technology Corp.


Issued Date : May 16, 2025
Page No. : 25 of 141



Report No.: 25030004

(New addition iron shell)
For ESY10I1E, Built-in PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025

: 26 of 141

Page No.



(New addition iron shell)
For ESY10I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


: 27 of 141

Page No.



(New addition iron shell) For ESY10I1E, Built-in PoE







Cerpass Technology Corp.

Issued Date : May 16, 2025
Page No. : 28 of 141



(New addition iron shell) For ESY10I1E, Built-in PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 29 of 141



(New addition iron shell)





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 30 of 141



(New addition iron shell)
For ESY10I1E, Built-in PoE







Cerpass Technology Corp.

Issued Date : May 16, 2025
Page No. : 31 of 141



(New addition iron shell) For ESY10I1E, Built-in PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025

Report No.: 25030004

Page No. : 32 of 141



(New addition iron shell) For ESY10I1E, Built-in PoE







Cerpass Technology Corp. Issued Date : May 16, 2025

Page No. : 33 of 141

(New addition iron shell)
For ESY10I1E, Built-in PoE







Cerpass Technology Corp.

Issued Date : May 16, 2025
Page No. : 34 of 141

(New addition iron shell)

For ESY10I1E, Built-in PoE






Cerpass Technology Corp.


Issued Date : May 16, 2025 Page No. : 35 of 141



Report No.: 25030004

(New addition iron shell) For ESY10I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025

Page No. : 36 of 141



Report No.: 25030004

(New addition iron shell)
For ESY10I1E, Built-in PoE






Cerpass Technology Corp.


Issued Date : May 16, 2025
Page No. : 37 of 141



Report No.: 25030004

(New addition iron shell)
For ESY10I1E, Built-in PoE






Cerpass Technology Corp.

Issued Date : May 16, 2025 Page No. : 38 of 141



Report No.: 25030004

(New addition iron shell) For ESY10I1E, Built-in PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025
Page No. : 39 of 141




Report No.: 25030004

(New addition iron shell)









Cerpass Technology Corp.

Issued Date : May 16, 2025 Page No. : 40 of 141



(New addition iron shell) For ESY10I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


: 41 of 141

Page No.



(New addition iron shell)
For ESY10I1E, Built-in PoE





Cerpass Technology Corp. Issued Date : May 16, 2025

Page No. : 42 of 141



(New addition iron shell) For ESY10I1E, Built-in PoE






Cerpass Technology Corp.

Issued Date : May 16, 2025 Page No. : 43 of 141



(New addition iron shell) For ESY10I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025
Page No. : 44 of 141



Report No.: 25030004

(New addition iron shell) For ESY10I1E, Built-in PoE




Cerpass Technology Corp.


Issued Date : May 16, 2025

Page No. : 45 of 141

(New addition iron shell) For ESY10I1E, Without PoE



ANT B position (For WLAN)




Cerpass Technology Corp.


Issued Date : May 16, 2025 Page No. : 46 of 141



Report No.: 25030004

(New addition iron shell)





Cerpass Technology Corp.


Issued Date : May 16, 2025 Page No. : 47 of 141



(New addition iron shell)

For ESY10I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


: 48 of 141

Page No.



(New addition iron shell)
For ESY10I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


: 49 of 141


Page No.



Report No.: 25030004

(New addition iron shell) For ESY10I1E, Without PoE






Cerpass Technology Corp.


Issued Date : May 16, 2025

Page No. : 50 of 141



(New addition iron shell)
For ESY10I1E, Without PoE






Cerpass Technology Corp. Issued Date : May 16, 2025


Page No. : 51 of 141



(New addition iron shell)

For ESY10I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 52 of 141



(New addition iron shell)
For ESY10I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025

: 53 of 141

Page No.

(New addition iron shell)
For ESY10I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004


Page No. : 54 of 141



(New addition iron shell)

For ESY10I1E, Without PoE







Cerpass Technology Corp.

Issued Date : May 16, 2025 Page No. : 55 of 141

(New addition iron shell)

For ESY10I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025

: 56 of 141

Page No.



(New addition iron shell)
For ESY10I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004


Page No. : 57 of 141



Report No.: 25030004

(New addition iron shell)
For ESY10I1E, Without PoE







Cerpass Technology Corp.

Issued Date : May 16, 2025 Page No. : 58 of 141



(New addition iron shell)





Cerpass Technology Corp. Issued Date : May 16, 2025


Page No. : 59 of 141



Report No.: 25030004

(New addition iron shell)
For ESY10I1E, Without PoE






Cerpass Technology Corp.

Issued Date : May 16, 2025
Page No. : 60 of 141



(New addition iron shell)






Cerpass Technology Corp.

Issued Date : May 16, 2025
Page No. : 61 of 141



Report No.: 25030004

(New addition iron shell) For ESY10I1E, Without PoE






Cerpass Technology Corp.

Issued Date : May 16, 2025 Page No. : 62 of 141



(New addition iron shell)
For ESY10I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025

: 63 of 141

Page No.