



(New addition iron shell)
For ESY22I1E, Built-in PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 103 of 141



(New addition iron shell)
For ESY22I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004


Page No. : 104 of 141



(New addition iron shell)

For ESY22I1E, Built-in PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 105 of 141



(New addition iron shell) For ESY22I1E, Built-in PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 106 of 141

(New addition iron shell)

For ESY22I1E, Built-in PoE






Cerpass Technology Corp.

Issued Date : May 16, 2025 Page No. : 107 of 141

Report No.: 25030004



(New addition iron shell)
For ESY22I1E, Built-in PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 108 of 141

ou addition iron aball)

(New addition iron shell) For ESY22I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004


Page No. : 109 of 141



Report No.: 25030004

(New addition iron shell) For ESY22I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Page No. : 110 of 141



Report No.: 25030004

(New addition iron shell) For ESY22I1E, Built-in PoE






Cerpass Technology Corp.

Issued Date : May 16, 2025

Page No. : 111 of 141



(New addition iron shell) For ESY22I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 112 of 141



Report No.: 25030004

(New addition iron shell) For ESY22I1E, Built-in PoE






Cerpass Technology Corp.

Issued Date : May 16, 2025 Page No. : 113 of 141



(New addition iron shell) For ESY22I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025

Report No.: 25030004

Page No. : 114 of 141



(New addition iron shell)
For ESY22I1E, Built-in PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 115 of 141



(New addition iron shell) For ESY22I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 116 of 141



(New addition iron shell) For ESY22I1E, Built-in PoE





Cerpass Technology Corp. Issued Date : May 16, 2025


Page No. : 117 of 141

Report No.: 25030004



Report No.: 25030004

(New addition iron shell) For ESY22I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Page No. : 118 of 141



(New addition iron shell)

For ESY22I1E, Without PoE






Cerpass Technology Corp.


Issued Date : May 16, 2025

Report No.: 25030004

Page No. : 119 of 141

(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 120 of 141



(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 121 of 141



(New addition iron shell)

For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004


Page No. : 122 of 141



NOLOGY CORP. Report No.: 25030004

(New addition iron shell)
For ESY22I1E, Without PoE






Cerpass Technology Corp.


Issued Date : May 16, 2025

Page No. : 123 of 141



(New addition iron shell)





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 124 of 141



(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 125 of 141



(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 126 of 141



(New addition iron shell)





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 127 of 141



(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004


Page No. : 128 of 141



(New addition iron shell)

For ESY22I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 129 of 141



(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


: 130 of 141

Page No.

Report No.: 25030004

(New addition iron shell)

For ESY22I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 131 of 141

Report No.: 25030004

(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025

Page No. : 132 of 141



Report No.: 25030004

(New addition iron shell) For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Page No. : 133 of 141



Report No.: 25030004

(New addition iron shell) For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


: 134 of 141

Page No.



Report No.: 25030004

(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025

Page No. : 135 of 141



Report No.: 25030004

(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025

Page No. : 136 of 141



Report No.: 25030004

(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025

Page No. : 137 of 141



(New addition iron shell)

For ESY22I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 138 of 141



(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025

Report No.: 25030004

Page No. : 139 of 141



(New addition iron shell)





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 140 of 141



Report No.: 25030004

(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025

Page No. : 141 of 141