


Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 268 of 833

802.11ax(HEW40)_MCH_6485MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_6485MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 269 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 270 of 833

802.11ax(HEW80)_LCH_6465MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_LCH_6465MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 271 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 272 of 833

2.2.5 OBW

802.11ax(HEW20)_LCH_6535MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_6535MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 273 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 274 of 833

802.11ax(HEW20)_MCH_6695MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_6695MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 275 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 276 of 833

802.11ax(HEW20)_HCH_6855MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_6855MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 277 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 278 of 833

802.11ax(HEW40)_LCH_6565MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_LCH_6565MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 279 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 280 of 833

802.11ax(HEW40)_MCH_6685MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_6685MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 281 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 282 of 833

802.11ax(HEW40)_HCH_6845MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_6845MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 283 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 284 of 833

802.11ax(HEW80)_LCH_6625MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_LCH_6625MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 285 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 286 of 833

802.11ax(HEW80)_MCH_6705MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_MCH_6705MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 287 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 288 of 833

802.11ax(HEW80)_HCH_6785MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_6785MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 289 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 290 of 833

802.11ax(HEW160)_MCH_6665MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_MCH_6665MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 291 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 292 of 833

2.2.6 26dB BW

802.11ax(HEW20)_LCH_6535MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_6535MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 293 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 294 of 833

802.11ax(HEW20)_MCH_6695MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_6695MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 295 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 296 of 833

802.11ax(HEW20)_HCH_6855MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_6855MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 297 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 298 of 833

802.11ax(HEW40)_LCH_6565MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_LCH_6565MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 299 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 300 of 833

802.11ax(HEW40)_MCH_6685MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_6685MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 301 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 302 of 833

802.11ax(HEW40)_HCH_6845MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_6845MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 303 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 304 of 833

802.11ax(HEW80)_LCH_6625MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_LCH_6625MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 305 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 306 of 833

802.11ax(HEW80)_MCH_6705MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_MCH_6705MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 307 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 308 of 833

802.11ax(HEW80)_HCH_6785MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_6785MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 309 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 310 of 833

802.11ax(HEW160)_MCH_6665MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_MCH_6665MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 311 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 312 of 833

2.2.7 OBW

802.11ax(HEW20)_LCH_6895MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_6895MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 313 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 314 of 833

802.11ax(HEW20)_MCH_6995MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_6995MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 315 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 316 of 833

802.11ax(HEW20)_HCH_7115MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_7115MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 317 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 318 of 833

802.11ax(HEW40)_LCH_6925MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_LCH_6925MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 319 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 320 of 833

802.11ax(HEW40)_MCH_7005MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_7005MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 321 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 322 of 833

802.11ax(HEW40)_HCH_7085MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_7085MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 323 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 324 of 833

802.11ax(HEW80)_LCH_6945MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_LCH_6945MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 325 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 326 of 833

802.11ax(HEW80)_HCH_7025MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_7025MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 327 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 328 of 833

802.11ax(HEW160)_MCH_6985MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_MCH_6985MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 329 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 330 of 833

2.2.8 26dB BW

802.11ax(HEW20)_LCH_6895MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_6895MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 331 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 332 of 833

802.11ax(HEW20)_MCH_6995MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_MCH_6995MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 333 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 334 of 833

802.11ax(HEW20)_HCH_7115MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_7115MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 335 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 336 of 833

802.11ax(HEW40)_LCH_6925MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_LCH_6925MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 337 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 338 of 833

802.11ax(HEW40)_MCH_7005MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_7005MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 339 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 340 of 833

802.11ax(HEW40)_HCH_7085MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_7085MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 341 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 342 of 833

802.11ax(HEW80)_LCH_6945MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_LCH_6945MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 343 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 344 of 833

802.11ax(HEW80)_HCH_7025MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_7025MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 345 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 346 of 833

802.11ax(HEW160)_MCH_6985MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_MCH_6985MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 347 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 348 of 833

2.2.9 OBW

802.11ax(HEW20)_HCH_6875MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_6875MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 349 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 350 of 833

802.11ax(HEW40)_HCH_6885MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_6885MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 351 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 352 of 833

802.11ax(HEW80)_HCH_6865MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_6865MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 353 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 354 of 833

802.11ax(HEW160)_HCH_6825MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_HCH_6825MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 355 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 356 of 833

2.2.10 26dB BW

802.11ax(HEW20)_HCH_6875MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_6875MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 357 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 358 of 833

802.11ax(HEW40)_HCH_6885MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_6885MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 359 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 360 of 833

802.11ax(HEW80)_HCH_6865MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_6865MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 361 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 362 of 833

802.11ax(HEW160)_HCH_6825MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_HCH_6825MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 363 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 364 of 833

2.2.11 OBW

802.11ax(HEW40)_HCH_6525MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_6525MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 365 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 366 of 833

802.11ax(HEW80)_HCH_6545MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_6545MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 367 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 368 of 833

802.11ax(HEW160)_HCH_6505MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_HCH_6505MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 369 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 370 of 833

2.2.12 26dB BW

802.11ax(HEW40)_HCH_6525MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_HCH_6525MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 371 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 372 of 833

802.11ax(HEW80)_HCH_6545MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_6545MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 373 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 374 of 833

802.11ax(HEW160)_HCH_6505MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_HCH_6505MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 375 of 833



Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 376 of 833

3. Maximum Conducted Output Power

3.1 Test Result

3.1.1 Power

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum Average Conducted Output Power (dBm)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	5955	RU242	Left	3.21	2.12	5.71	/	Pass
			6175	RU242	Left	3.32	2.66	6.01	/	Pass
			6415	RU242	Left	3.66	4.28	6.99	/	Pass
	802.11ax (HEW40)	MIMO	5965	RU484	Left	4.90	3.20	7.14	/	Pass
			6165	RU484	Left	5.23	3.83	7.60	/	Pass
			6405	RU484	Left	5.26	6.44	8.90	/	Pass
	802.11ax (HEW80)	MIMO	5985	RU996	Left	4.54	3.09	6.89	/	Pass
			6145	RU996	Left	4.67	2.85	6.86	/	Pass
			6385	RU996	Left	4.63	5.29	7.98	/	Pass
	802.11ax (HEW160)	MIMO	6025	2xRU996	Left	1.85	1.21	4.55	/	Pass
			6185	2xRU996	Left	1.99	0.63	4.37	/	Pass
			6345	2xRU996	Left	1.74	2.19	4.98	/	Pass
Note1: Antenna Gain: Ant1: 2.85dBi; Ant5: 2.92dBi;										

3.1.2 EIRP

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	E.I.R.P (dBm)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	5955	RU242	Left	6.06	5.04	8.59	<=24	Pass
			6175	RU242	Left	6.17	5.58	8.90	<=24	Pass
			6415	RU242	Left	6.51	7.20	9.88	<=24	Pass
	802.11ax	MIMO	5965	RU484	Left	7.75	6.12	10.02	<=24	Pass

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 377 of 833

	(HEW40)		6165	RU484	Left	8.08	6.75	10.48	<=24	Pass
			6405	RU484	Left	8.11	9.36	11.79	<=24	Pass
	802.11ax (HEW80)	MIMO	5985	RU996	Left	7.39	6.01	9.76	<=24	Pass
			6145	RU996	Left	7.52	5.77	9.74	<=24	Pass
			6385	RU996	Left	7.48	8.21	10.87	<=24	Pass
	802.11ax (HEW160)	MIMO	6025	2xRU996	Left	4.70	4.13	7.43	<=24	Pass
			6185	2xRU996	Left	4.84	3.55	7.25	<=24	Pass
			6345	2xRU996	Left	4.59	5.11	7.87	<=24	Pass
Note1: Antenna Gain: Ant1: 2.85dBi; Ant5: 2.92dBi; Note2: E.I.R.P = Measured Power + Antenna Gain										

3.1.3 Power

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum Average Conducted Output Power (dBm)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	6435	RU242	Left	3.33	3.22	6.29	/	Pass
			6475	RU242	Left	3.52	4.51	7.05	/	Pass
			6515	RU242	Left	3.50	4.99	7.32	/	Pass
	802.11ax (HEW40)	MIMO	6445	RU484	Left	4.61	6.35	8.58	/	Pass
			6485	RU484	Left	5.07	6.45	8.82	/	Pass
	802.11ax (HEW80)	MIMO	6465	RU996	Left	4.31	5.27	7.83	/	Pass
Note1: Antenna Gain: Ant1: 1.75dBi; Ant5: 2.26dBi;										

3.1.4 EIRP

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	E.I.R.P (dBm)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	6435	RU242	Left	5.08	5.48	8.29	<=24	Pass
			6475	RU242	Left	5.27	6.77	9.09	<=24	Pass

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 378 of 833

			6515	RU242	Left	5.25	7.25	9.37	<=24	Pass
	802.11ax (HEW40)	MIMO	6445	RU484	Left	6.36	8.61	10.64	<=24	Pass
			6485	RU484	Left	6.82	8.71	10.88	<=24	Pass
	802.11ax (HEW80)	MIMO	6465	RU996	Left	6.06	7.53	9.87	<=24	Pass

Note1: Antenna Gain: Ant1: 1.75dBi; Ant5: 2.26dBi;
Note2: E.I.R.P = Measured Power + Antenna Gain

3.1.5 Power

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum Average Conducted Output Power (dBm)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	6535	RU242	Left	3.69	5.12	7.47	/	Pass
			6695	RU242	Left	3.47	5.44	7.58	/	Pass
			6855	RU242	Left	3.68	3.09	6.41	/	Pass
	802.11ax (HEW40)	MIMO	6565	RU484	Left	5.33	5.04	8.20	/	Pass
			6685	RU484	Left	3.88	4.32	7.12	/	Pass
			6845	RU484	Left	5.38	6.23	8.84	/	Pass
	802.11ax (HEW80)	MIMO	6625	RU996	Left	5.54	6.28	8.94	/	Pass
			6705	RU996	Left	4.82	5.32	8.09	/	Pass
			6785	RU996	Left	4.26	4.80	7.55	/	Pass
	802.11ax (HEW160)	MIMO	6665	2xRU996	Left	2.38	3.67	6.08	/	Pass

Note1: Antenna Gain: Ant1: 2.48dBi; Ant5: 2.19dBi;

3.1.6 EIRP

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	E.I.R.P (dBm)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax	MIMO	6535	RU242	Left	6.17	7.31	9.79	<=24	Pass

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum Average Conducted Output Power (dBm)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	6895	RU242	Left	3.99	2.95	6.51	/	Pass
			6995	RU242	Left	2.36	4.39	6.50	/	Pass
			7115	RU242	Left	2.25	3.03	5.67	/	Pass
	802.11ax (HEW40)	MIMO	6925	RU484	Left	4.92	6.33	8.69	/	Pass
			7005	RU484	Left	3.73	6.39	8.27	/	Pass
			7085	RU484	Left	3.70	4.83	7.31	/	Pass
	802.11ax (HEW80)	MIMO	6945	RU996	Left	4.79	5.91	8.40	/	Pass
			7025	RU996	Left	3.85	5.46	7.74	/	Pass
	802.11ax (HEW160)	MIMO	6985	2xRU996	Left	1.10	3.14	5.25	/	Pass

Note1: Antenna Gain: Ant1: 1.88dBi; Ant5: 2.07dBi;

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum Average Conducted Output Power (dBm)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	6875	RU242	Left	4.25	2.53	6.48	/	Pass
	802.11ax (HEW40)	MIMO	6885	RU484	Left	5.68	4.01	7.94	/	Pass
	802.11ax (HEW80)	MIMO	6865	RU996	Left	5.22	3.75	7.56	/	Pass
	802.11ax (HEW160)	MIMO	6825	2xRU996	Left	2.48	2.70	5.60	/	Pass
Note1: Antenna Gain: Ant1: 2.48dBi; Ant5: 2.19dBi;										

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 381 of 833

3.1.10 EIRP

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	E.I.R.P (dBm)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	6875	RU242	Left	6.73	4.72	8.85	<=24	Pass
	802.11ax (HEW40)	MIMO	6885	RU484	Left	8.16	6.20	10.30	<=24	Pass
	802.11ax (HEW80)	MIMO	6865	RU996	Left	7.70	5.94	9.92	<=24	Pass
	802.11ax (HEW160)	MIMO	6825	2xRU996	Left	4.96	4.89	7.94	<=24	Pass
Note1: Antenna Gain: Ant1: 2.48dBi; Ant5: 2.19dBi; Note2: E.I.R.P = Measured Power + Antenna Gain										

3.1.11 Power

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum Average Conducted Output Power (dBm)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW40)	MIMO	6525	RU484	Left	5.27	6.19	8.76	/	Pass
	802.11ax (HEW80)	MIMO	6545	RU996	Left	4.92	6.09	8.55	/	Pass
	802.11ax (HEW160)	MIMO	6505	2xRU996	Left	2.23	2.70	5.48	/	Pass
Note1: Antenna Gain: Ant1: 2.48dBi; Ant5: 2.26dBi;										

3.1.12 EIRP

ENV	Mode	TX	Frequency	RU	RU	E.I.R.P (dBm)	Verdict
-----	------	----	-----------	----	----	---------------	---------



Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 382 of 833

		Type	(MHz)		Pos	ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW40)	MIMO	6525	RU484	Left	7.75	8.45	11.12	<=24	Pass
	802.11ax (HEW80)	MIMO	6545	RU996	Left	7.40	8.35	10.91	<=24	Pass
	802.11ax (HEW160)	MIMO	6505	2xRU996	Left	4.71	4.96	7.85	<=24	Pass

Note1: Antenna Gain: Ant1: 2.48dBi; Ant5: 2.26dBi;

Note2: E.I.R.P = Measured Power + Antenna Gain

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 383 of 833

4. Maximum Power Spectral Density

4.1 Test Result

4.1.1 PSD

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum PSD (dBm/MHz)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	5955	RU242	Left	-8.67	-8.89	-5.95	/	Pass
			6175	RU242	Left	-8.14	-8.60	-5.67	/	Pass
			6415	RU242	Left	-7.88	-6.47	-4.54	/	Pass
	802.11ax (HEW40)	MIMO	5965	RU484	Left	-9.92	-10.60	-7.59	/	Pass
			6165	RU484	Left	-9.37	-10.06	-7.08	/	Pass
			6405	RU484	Left	-9.17	-7.71	-5.82	/	Pass
	802.11ax (HEW80)	MIMO	5985	RU996	Left	-12.67	-13.71	-10.90	/	Pass
			6145	RU996	Left	-12.74	-14.01	-10.77	/	Pass
			6385	RU996	Left	-13.16	-12.05	-9.86	/	Pass
	802.11ax (HEW160)	MIMO	6025	2xRU996	Left	-17.70	-18.41	-15.64	/	Pass
			6185	2xRU996	Left	-17.87	-18.62	-15.97	/	Pass
			6345	2xRU996	Left	-18.42	-17.91	-15.56	/	Pass
Note1: Antenna Gain: Ant1: 2.85dBi; Ant5: 2.92dBi;										

4.1.2 E.I.R.PSD

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum E.I.R.PSD (dBm/MHz)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	5955	RU242	Left	-5.82	-5.97	-2.88	<=-1	Pass
			6175	RU242	Left	-5.29	-5.68	-2.47	<=-1	Pass
			6415	RU242	Left	-5.03	-3.55	-1.22	<=-1	Pass
	802.11ax (HEW40)	MIMO	5965	RU484	Left	-7.07	-7.68	-4.35	<=-1	Pass
			6165	RU484	Left	-6.52	-7.14	-3.81	<=-1	Pass

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 384 of 833

			6405	RU484	Left	-6.32	-4.79	-2.48	<=-1	Pass
	802.11ax (HEW80)	MIMO	5985	RU996	Left	-9.82	-10.79	-7.27	<=-1	Pass
			6145	RU996	Left	-9.89	-11.09	-7.44	<=-1	Pass
			6385	RU996	Left	-10.31	-9.13	-6.67	<=-1	Pass
			802.11ax (HEW160)	MIMO	6025	2xRU996	Left	-14.85	-15.49	-12.15
	6185	2xRU996			Left	-15.02	-15.70	-12.34	<=-1	Pass
	6345	2xRU996			Left	-15.57	-14.99	-12.26	<=-1	Pass
Note1: Antenna Gain: Ant1: 2.85dBi; Ant5: 2.92dBi; Note2: E.I.R.PSD = Measured PSD + Antenna Gain										

4.1.3 PSD

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum PSD (dBm/MHz)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	6435	RU242	Left	-8.39	-7.29	-5.42	/	Pass
			6475	RU242	Left	-8.16	-6.27	-4.61	/	Pass
			6515	RU242	Left	-8.18	-5.65	-4.04	/	Pass
	802.11ax (HEW40)	MIMO	6445	RU484	Left	-9.85	-7.78	-6.07	/	Pass
			6485	RU484	Left	-9.41	-7.21	-5.73	/	Pass
	802.11ax (HEW80)	MIMO	6465	RU996	Left	-13.21	-11.65	-9.42	/	Pass
Note1: Antenna Gain: Ant1: 1.75dBi; Ant5: 2.26dBi;										

4.1.4 E.I.R.PSD

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum E.I.R.PSD (dBm/MHz)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	6435	RU242	Left	-6.64	-5.03	-2.75	<=-1	Pass
			6475	RU242	Left	-6.41	-4.01	-2.04	<=-1	Pass
			6515	RU242	Left	-6.43	-3.39	-1.64	<=-1	Pass
	802.11ax	MIMO	6445	RU484	Left	-8.10	-5.52	-3.61	<=-1	Pass

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 385 of 833

	(HEW40)		6485	RU484	Left	-7.66	-4.95	-3.09	<=-1	Pass
	802.11ax (HEW80)	MIMO	6465	RU996	Left	-11.46	-9.39	-7.29	<=-1	Pass
Note1: Antenna Gain: Ant1: 1.75dBi; Ant5: 2.26dBi; Note2: E.I.R.PSD = Measured PSD + Antenna Gain										

4.1.5 PSD

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum PSD (dBm/MHz)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	6535	RU242	Left	-7.92	-5.42	-4.00	/	Pass
			6695	RU242	Left	-7.92	-5.39	-4.10	/	Pass
			6855	RU242	Left	-7.89	-7.86	-5.46	/	Pass
	802.11ax (HEW40)	MIMO	6565	RU484	Left	-9.37	-8.85	-6.59	/	Pass
			6685	RU484	Left	-10.60	-10.02	-7.47	/	Pass
			6845	RU484	Left	-9.12	-7.66	-5.85	/	Pass
	802.11ax (HEW80)	MIMO	6625	RU996	Left	-12.02	-10.80	-8.85	/	Pass
			6705	RU996	Left	-12.60	-13.30	-10.17	/	Pass
			6785	RU996	Left	-13.08	-11.54	-10.05	/	Pass
	802.11ax (HEW160)	MIMO	6665	2xRU996	Left	-18.35	-16.01	-14.44	/	Pass
Note1: Antenna Gain: Ant1: 2.48dBi; Ant5: 2.19dBi;										

4.1.6 E.I.R.PSD

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum E.I.R.PSD (dBm/MHz)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	6535	RU242	Left	-5.44	-3.23	-1.19	<=-1	Pass
			6695	RU242	Left	-5.44	-3.20	-1.17	<=-1	Pass
			6855	RU242	Left	-5.41	-5.67	-2.53	<=-1	Pass
	802.11ax	MIMO	6565	RU484	Left	-6.89	-6.66	-3.76	<=-1	Pass

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 386 of 833

	(HEW40)		6685	RU484	Left	-8.12	-7.83	-4.96	<=-1	Pass
			6845	RU484	Left	-6.64	-5.47	-3.01	<=-1	Pass
	802.11ax (HEW80)	MIMO	6625	RU996	Left	-9.54	-8.61	-6.04	<=-1	Pass
			6705	RU996	Left	-10.12	-11.11	-7.58	<=-1	Pass
			6785	RU996	Left	-10.60	-9.35	-6.92	<=-1	Pass
	802.11ax (HEW160)	MIMO	6665	2xRU996	Left	-15.87	-13.82	-11.71	<=-1	Pass
Note1: Antenna Gain: Ant1: 2.48dBi; Ant5: 2.19dBi; Note2: E.I.R.PSD = Measured PSD + Antenna Gain										

4.1.7 PSD

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum PSD (dBm/MHz)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	6895	RU242	Left	-7.42	-7.79	-5.36	/	Pass
			6995	RU242	Left	-9.32	-6.20	-4.81	/	Pass
			7115	RU242	Left	-9.19	-7.48	-5.74	/	Pass
	802.11ax (HEW40)	MIMO	6925	RU484	Left	-9.64	-7.63	-6.03	/	Pass
			7005	RU484	Left	-10.91	-7.17	-5.96	/	Pass
			7085	RU484	Left	-11.06	-9.04	-7.11	/	Pass
	802.11ax (HEW80)	MIMO	6945	RU996	Left	-12.67	-10.70	-9.10	/	Pass
			7025	RU996	Left	-13.57	-11.10	-9.53	/	Pass
	802.11ax (HEW160)	MIMO	6985	2xRU996	Left	-19.75	-16.50	-15.22	/	Pass
Note1: Antenna Gain: Ant1: 1.88dBi; Ant5: 2.07dBi;										

4.1.8 E.I.R.PSD

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum E.I.R.PSD (dBm/MHz)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax	MIMO	6895	RU242	Left	-5.54	-5.72	-2.62	<=-1	Pass

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 387 of 833

	(HEW20)		6995	RU242	Left	-7.44	-4.13	-2.47	<=-1	Pass
			7115	RU242	Left	-7.31	-5.41	-3.25	<=-1	Pass
	802.11ax (HEW40)	MIMO	6925	RU484	Left	-7.76	-5.56	-3.51	<=-1	Pass
			7005	RU484	Left	-9.03	-5.10	-3.62	<=-1	Pass
			7085	RU484	Left	-9.18	-6.97	-4.93	<=-1	Pass
	802.11ax (HEW80)	MIMO	6945	RU996	Left	-10.79	-8.63	-6.57	<=-1	Pass
			7025	RU996	Left	-11.69	-9.03	-7.15	<=-1	Pass
	802.11ax (HEW160)	MIMO	6985	2xRU996	Left	-17.87	-14.43	-12.81	<=-1	Pass
Note1: Antenna Gain: Ant1: 1.88dBi; Ant5: 2.07dBi; Note2: E.I.R.PSD = Measured PSD + Antenna Gain										

4.1.9 PSD

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum PSD (dBm/MHz)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW20)	MIMO	6875	RU242	Left	-7.29	-8.37	-5.38	/	Pass
	802.11ax (HEW40)	MIMO	6885	RU484	Left	-8.78	-10.03	-6.65	/	Pass
	802.11ax (HEW80)	MIMO	6865	RU996	Left	-12.06	-13.00	-9.99	/	Pass
	802.11ax (HEW160)	MIMO	6825	2xRU996	Left	-17.82	-16.33	-14.61	/	Pass
Note1: Antenna Gain: Ant1: 2.48dBi; Ant5: 2.19dBi;										

4.1.10 E.I.R.PSD

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum E.I.R.PSD (dBm/MHz)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax	MIMO	6875	RU242	Left	-4.81	-6.18	-2.43	<=-1	Pass

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 388 of 833

	(HEW20)									
	802.11ax (HEW40)	MIMO	6885	RU484	Left	-6.30	-7.84	-3.99	<=-1	Pass
	802.11ax (HEW80)	MIMO	6865	RU996	Left	-9.58	-10.81	-7.14	<=-1	Pass
	802.11ax (HEW160)	MIMO	6825	2xRU996	Left	-15.34	-14.14	-11.69	<=-1	Pass
Note1: Antenna Gain: Ant1: 2.48dBi; Ant5: 2.19dBi; Note2: E.I.R.PSD = Measured PSD + Antenna Gain										

4.1.11 PSD

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum PSD (dBm/MHz)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW40)	MIMO	6525	RU484	Left	-9.28	-7.60	-5.98	/	Pass
	802.11ax (HEW80)	MIMO	6545	RU996	Left	-12.46	-10.67	-8.89	/	Pass
	802.11ax (HEW160)	MIMO	6505	2xRU996	Left	-17.89	-16.59	-14.53	/	Pass
Note1: Antenna Gain: Ant1: 2.48dBi; Ant5: 2.26dBi;										

4.1.12 E.I.R.PSD

ENV	Mode	TX Type	Frequency (MHz)	RU	RU Pos	Maximum E.I.R.PSD (dBm/MHz)				Verdict
						ANT1	ANT5	MIMO	Limit	
NTNV	802.11ax (HEW40)	MIMO	6525	RU484	Left	-6.80	-5.34	-3.00	<=-1	Pass
	802.11ax (HEW80)	MIMO	6545	RU996	Left	-9.98	-8.41	-6.11	<=-1	Pass
	802.11ax	MIMO	6505	2xRU996	Left	-15.41	-14.33	-11.83	<=-1	Pass



Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 389 of 833

	(HEW160)									
Note1: Antenna Gain: Ant1: 2.48dBi; Ant5: 2.26dBi; Note2: E.I.R.PSD = Measured PSD + Antenna Gain										

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023


Report No.: KSCR240700121706

Page: 390 of 833

4.2 Test Graph

4.2.1 PSD

802.11ax(HEW20)_LCH_5955MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_5955MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 391 of 833




802.11ax(HEW20) LCH_5955MHz_RU242_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 392 of 833




802.11ax(HEW20) MCH_6175MHz_RU242_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 393 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 394 of 833

802.11ax(HEW20)_MCH_6175MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_MCH_6175MHz_RU242_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 395 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 396 of 833

802.11ax(HEW20)_HCH_6415MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_6415MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 397 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 398 of 833

802.11ax(HEW20)_HCH_6415MHz_RU242_Left_MIMO_NTNV




802.11ax(HEW40)_LCH_5965MHz_RU484_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 399 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 400 of 833

802.11ax(HEW40)_LCH_5965MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW40)_LCH_5965MHz_RU484_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 401 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 402 of 833

802.11ax(HEW40)_MCH_6165MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_6165MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 403 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 404 of 833

802.11ax(HEW40)_MCH_6165MHz_RU484_Left_MIMO_NTNV




802.11ax(HEW40)_HCH_6405MHz_RU484_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 405 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 406 of 833

802.11ax(HEW40)_HCH_6405MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW40)_HCH_6405MHz_RU484_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 407 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 408 of 833

802.11ax(HEW80)_LCH_5985MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_LCH_5985MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 409 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 410 of 833

802.11ax(HEW80)_LCH_5985MHz_RU996_Left_MIMO_NTNV




802.11ax(HEW80)_MCH_6145MHz_RU996_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 411 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 412 of 833

802.11ax(HEW80)_MCH_6145MHz_RU996_Left_Ant5_NTNV




802.11ax(HEW80)_MCH_6145MHz_RU996_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 413 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 414 of 833

802.11ax(HEW80)_HCH_6385MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_6385MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 415 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 416 of 833

802.11ax(HEW80)_HCH_6385MHz_RU996_Left_MIMO_NTNV




802.11ax(HEW160)_LCH_6025MHz_2xRU996_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 417 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 418 of 833

802.11ax(HEW160)_LCH_6025MHz_2xRU996_Left_Ant5_NTNV




802.11ax(HEW160)_LCH_6025MHz_2xRU996_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 419 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 420 of 833

802.11ax(HEW160)_MCH_6185MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_MCH_6185MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 421 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 422 of 833

802.11ax(HEW160)_MCH_6185MHz_2xRU996_Left_MIMO_NTNV




802.11ax(HEW160)_HCH_6345MHz_2xRU996_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 423 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 424 of 833

802.11ax(HEW160)_HCH_6345MHz_2xRU996_Left_Ant5_NTNV




802.11ax(HEW160)_HCH_6345MHz_2xRU996_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 425 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 426 of 833

4.2.2 E.I.R.PSD

802.11ax(HEW20)_LCH_5955MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_5955MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 427 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 428 of 833

802.11ax(HEW20)_LCH_5955MHz_RU242_Left_MIMO_NTNV




802.11ax(HEW20)_MCH_6175MHz_RU242_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 429 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 430 of 833

802.11ax(HEW20)_MCH_6175MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_MCH_6175MHz_RU242_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 431 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 432 of 833

802.11ax(HEW20)_HCH_6415MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_6415MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 433 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 434 of 833

802.11ax(HEW20)_HCH_6415MHz_RU242_Left_MIMO_NTNV




802.11ax(HEW40)_LCH_5965MHz_RU484_Left Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 435 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 436 of 833

802.11ax(HEW40)_LCH_5965MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW40)_LCH_5965MHz_RU484_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 437 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 438 of 833

802.11ax(HEW40)_MCH_6165MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_6165MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 439 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 440 of 833

802.11ax(HEW40)_MCH_6165MHz_RU484_Left_MIMO_NTNV




802.11ax(HEW40)_HCH_6405MHz_RU484_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 441 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 442 of 833

802.11ax(HEW40)_HCH_6405MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW40)_HCH_6405MHz_RU484_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 443 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 444 of 833

802.11ax(HEW80)_LCH_5985MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_LCH_5985MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 445 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 446 of 833

802.11ax(HEW80)_LCH_5985MHz_RU996_Left_MIMO_NTNV




802.11ax(HEW80)_MCH_6145MHz_RU996_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 447 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 448 of 833

802.11ax(HEW80)_MCH_6145MHz_RU996_Left_Ant5_NTNV




802.11ax(HEW80)_MCH_6145MHz_RU996_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 449 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 450 of 833

802.11ax(HEW80)_HCH_6385MHz_RU996_Left_Ant1_NTNV




802.11ax(HEW80)_HCH_6385MHz_RU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 451 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 452 of 833

802.11ax(HEW80)_HCH_6385MHz_RU996_Left_MIMO_NTNV




802.11ax(HEW160)_LCH_6025MHz_2xRU996_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 453 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 454 of 833

802.11ax(HEW160)_LCH_6025MHz_2xRU996_Left_Ant5_NTNV




802.11ax(HEW160)_LCH_6025MHz_2xRU996_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 455 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 456 of 833

802.11ax(HEW160)_MCH_6185MHz_2xRU996_Left_Ant1_NTNV




802.11ax(HEW160)_MCH_6185MHz_2xRU996_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 457 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 458 of 833

802.11ax(HEW160)_MCH_6185MHz_2xRU996_Left_MIMO_NTNV




802.11ax(HEW160)_HCH_6345MHz_2xRU996_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 459 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 460 of 833

802.11ax(HEW160)_HCH_6345MHz_2xRU996_Left_Ant5_NTNV




802.11ax(HEW160)_HCH_6345MHz_2xRU996_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 461 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 462 of 833

4.2.3 PSD

802.11ax(HEW20)_LCH_6435MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_6435MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 463 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 464 of 833

802.11ax(HEW20)_LCH_6435MHz_RU242_Left_MIMO_NTNV




802.11ax(HEW20)_MCH_6475MHz_RU242_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 465 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 466 of 833

802.11ax(HEW20)_MCH_6475MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_MCH_6475MHz_RU242_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 467 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 468 of 833

802.11ax(HEW20)_HCH_6515MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_6515MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 469 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 470 of 833

802.11ax(HEW20)_HCH_6515MHz_RU242_Left_MIMO_NTNV




802.11ax(HEW40)_LCH_6445MHz_RU484_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 471 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 472 of 833

802.11ax(HEW40)_LCH_6445MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW40)_LCH_6445MHz_RU484_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 473 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 474 of 833

802.11ax(HEW40)_MCH_6485MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_6485MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 475 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 476 of 833

802.11ax(HEW40)_MCH_6485MHz_RU484_Left_MIMO_NTNV




802.11ax(HEW80)_LCH_6465MHz_RU996_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 477 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 478 of 833

802.11ax(HEW80)_LCH_6465MHz_RU996_Left_Ant5_NTNV




802.11ax(HEW80)_LCH_6465MHz_RU996_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 479 of 833



Compliance Certification Services (Kunshan) Inc.


CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 480 of 833

4.2.4 E.I.R.PSD

802.11ax(HEW20)_LCH_6435MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_LCH_6435MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 481 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 482 of 833

802.11ax(HEW20)_LCH_6435MHz_RU242_Left_MIMO_NTNV




802.11ax(HEW20)_MCH_6475MHz_RU242_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 483 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 484 of 833

802.11ax(HEW20)_MCH_6475MHz_RU242_Left_Ant5_NTNV




802.11ax(HEW20)_MCH_6475MHz_RU242_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 485 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 486 of 833

802.11ax(HEW20)_HCH_6515MHz_RU242_Left_Ant1_NTNV




802.11ax(HEW20)_HCH_6515MHz_RU242_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 487 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 488 of 833

802.11ax(HEW20)_HCH_6515MHz_RU242_Left_MIMO_NTNV




802.11ax(HEW40)_LCH_6445MHz_RU484_Left Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 489 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 490 of 833

802.11ax(HEW40)_LCH_6445MHz_RU484_Left_Ant5_NTNV




802.11ax(HEW40)_LCH_6445MHz_RU484_Left_MIMO_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 491 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 492 of 833

802.11ax(HEW40)_MCH_6485MHz_RU484_Left_Ant1_NTNV




802.11ax(HEW40)_MCH_6485MHz_RU484_Left_Ant5_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 493 of 833




Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 494 of 833

802.11ax(HEW40)_MCH_6485MHz_RU484_Left_MIMO_NTNV



802.11ax(HEW80)_LCH_6465MHz_RU996_Left_Ant1_NTNV

Compliance Certification Services (Kunshan) Inc.

CCSEM-TRF-001 Rev. 02 Sep 01, 2023

Report No.: KSCR240700121706

Page: 495 of 833

