

From: JHarrington@f2labs.com
Sent: Tuesday, August 03, 2004 1:03 PM
To: Clark, Randy
Subject: Photograph changes for MCSB listing.

Three new photographs have been supplied to replace those in the original listing.

The photographs depict the EUT in an arrangement more consistent with how it was assessed. That is, they show that the battery cable leaves the MCSB enclosure directly rather than have excessive amounts of cable bundled up inside the enclosure.

Having large amounts of cable in the enclosure increases the likelihood that RF signals inside the enclosure could couple to the cable and be conducted outside of the enclosure where they could re radiate to the detriment of the EUT's spurious emissions performance.

No component changes have been made.

Sincerely

John Harrington
EMC Technical Manager
F Squared Laboratories