

INTERTEK TESTING SERVICES

Report No.: 0316373
Model No.: JN-394

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement

HP

REF -20.0 dBm

AT 10 dB

MARK 17.813 msec


.05 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: K1
(Kenneth Wong)

Date: 10/10/03

Checked By: [Signature]
(Ivan)

Date: 17/10

Test Result: Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec

Report No.: 0316373
Model No.: JN-394

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

MKR 17.775 msec

REF -20.0 dBm

AT 10 dB


.00 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By:

(Kevin Wong)

Date:

10/10/03

Checked By:

(Van)

Date:

17/0

Test Result : Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

Report No.: 0316373
Model No.: JN-394

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement

MKR 1.4250 msec

REF -20.0 dBm

AT 10 dB


-.02 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: KL
(Kermit Wong)

Date: 10/10/03

Checked By: [Signature]
(Tuan)

Date: 17/10

Test Result: Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

Report No.: 0316373
Model No.: JN-394

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

MKA 450.00 μ sec

REF -20.0 dBm

AT 10 dB


-.07 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By:

LL
Kenneth Wong

Date:

10/10/03

Checked By:

[Signature]
(10/10/03)

Date:

17/10

Test Result : Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec