

INTERTEK TESTING SERVICES


Report No.: 0405612
Model No.: JN-404

hp

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement MKR 17.438 msec

REF -30.0 dBm AT 10 dB - .05 dB

PEAK
LOG
10
dB/



WA SB
SC LS
CORR

Tested By: *[Signature]*
(Tung Li)

Date: 13-4-04

Checked By: *[Signature]*
(100m)

Date: 16/4/04

Test Result: Pass / Fail / NA

CENTER 49.861 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec

INTERTEK TESTING SERVICES

Report No.: 0405672
Model No.: JN-404

hp

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement MKR 17.400 msec

REF -30.0 dBm

AT 10 dB


.02 dB

PEAK

LOG

10

dB/



WA SB

SC LS

CORR

Tested By: *[Signature]*
(Tony Li)

Date: 13-4-04

Checked By: *[Signature]*
(1000)

Date: 16/4/04

Test Result: Pass / Fail / NA

CENTER 49.861 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

INTERTEK TESTING SERVICES

Report No.: 0405672
Model No.: JV-404

hp


Pursuant to FCC Part 15 Section 15.235 Emissions Requirement MKR 1.4250 msec

REF -30.0 dBm

AT 10 dB

.09 dB

PEAK
LOG
10
dB/



WA SB
SC LS
CORR

Tested By: (Signature)

Date: 13-4-04

Checked By: (Signature)

Date: 16/4/04

Test Result: Pass / Fail / NA

CENTER 49.861 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

INTERTEK TESTING SERVICES

hp

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

MKR 450.00 μ sec

Report No.: 040872

Model No.: JN-404

REF -30.0 dBm

AT 10 dB


.10 dB

PEAK

LOG

10

dB/



WA SB

SC LS

CORR

Tested By: *[Signature]*
(Ching Li)

Date: 12-4-04

Checked By: *[Signature]*
(1000)

Date: 16/4/04

Test Result : Pass / Fail / NA

CENTER 49.861 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec