
May 28, 2004
Federal Communications Commission
Equipment Approval Services
7435 Oakland Mills Road
Columbia, MD 21046

SUBJECT : Techsan I&C Co., Ltd.
FCC ID: RJ5LM15
FCC Part 15 Subpart B Certification


Gentlemen:

Transmitted herewith, on behalf Techsan I&C Co., Ltd. is an application for a FCC Part 15 Subpart B Certification of the following 15-inch LCD Monitor :

FCC ID : RJ5LM15
Models No. : LM1530A, LM1535A, LM1540A, LM1545A

Attached is the applicant's Cover Letter, External/Internal Photos, Test Set-Up Photos, FCC ID & Label Location, User Manual, Block Diagram and Test Report.

Should you have any questions or comments concerning the above, please contact the undersigned.



KI SOO KIM (kisookim@hct.co.kr, 82-31-639-8506)
EMC MANAGER

cc: Mr. IN SUNG SHIM ----- Quality Control Team / GENERAL MANAGER

• Solution for EMI

We, TECHSAN I & C CO., LTD. , announce that all modifications will be incorporated into each unit sold in the U.S.

1. Attach a ferrite core to the OSD signal interface cable
2. Attach a piece of copper foil by bridging it from the LCD panel frame to the OSD board
3. Attach a conductive gasket at the LCD's rear panel

(Please refer to next page of the photographs for Solution for EMI)

TECHSAN I & C CO., LTD.

2004. 5. 28

Quality Control Team / GENERAL MANAGER

isshim@techsan.co.kr , 82-31-665-7190(210)

IN SUNG SHIM



1. Apply a ferrite core to the OSD signal interface cable



2. Attach a piece of copper foil by bridging it from the LCD panel frame to the OSD board



3. Attach a conductive gasket at the LCD's rear panel

