



APPENDIX 1: Photographs of test setup


RF Power(None Combiner(HX69-C))




RF Power(With Combiner(HX69-C))




Modulation Characteristics



Emission Bandwidth(None Combiner(HX69-C))



(With Combiner(HX69-C))



UL Apex Co., Ltd.

Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116



Facsimile : +81 596 24 8124

MF060b(10.04.03)



Spurious Emission at Antenna Terminals



Field Strength of Spurious Emission(None Combiner(HX69-C))



Field Strength of Spurious Emission(With Combiner(HX69-C))



UL Apex Co., Ltd.

Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116


Facsimile : +81 596 24 8124

MF060b(10.04.03)

Frequency Stability



Transient Frequency Behavior



UL Apex Co., Ltd.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116

Facsimile : +81 596 24 8124

MF060b(10.04.03)