


This message is not flagged. [[Flag Message](#) - [Mark as Unread](#)]

From: "Randal Clark" <randy.clark@ckccertification.com>  [Add to Address Book](#)
To: "'Monika Brandle'" <monikabrandle@yahoo.com>
Subject: RE: Non-Conformities FCC ID: (Ref # E04-00002-1)
Date: Mon, 8 Mar 2004 10:34:40 -0800

Thank you Mo,

I took a look at the confidentiality letter with the customer this morning. It appears that what he is requesting is legitimate. He worded the letter calling the schematics, block diagrams and PCB etchings "Photos" Could you take another look at that and make sure i'm not missing something.

I'm looking into the measurements under 30MHz issue. Something came out about this recently; if they used a bicon down to 20 MHz and it was calibrated to that frequency, then i do not think there's a problem. -- I'll check around for some things.

Thanks,
Randy.

-----Original Message-----

From: Monika Brandle [mailto:monikabrandle@yahoo.com]
Sent: Monday, March 08, 2004 6:38 AM
To: tom.mazzola@eadstelecom-na.com
Cc: info@ckccertification.com
Subject: Non-Conformities FCC ID: (Ref # E04-00002-1)

The following items are still needed to complete the evaluation for your product. Please send this information to info@ckccertification.com.

- Item 1. Please upload a signed copy of the Indemnification and Liability Statement. An example has been provided.
- Item 2. Please provide an updated label using the new format US:
ABCWT02B12345678
Where: ABC- Responsible Party Code (RPC)
WT- Equipment Code
02B - AC Ringer Equivalence Number (REN)
12345678-Product Identifier
- Item 3. Please provide the following for the US service agent.
Company Name
Individual or Department
Address

City, State, Zip
Phone
URL:

- Item 4. Please confirm/answer the following questions
- Network address signaling code
 - AC Ringer Equivalence Number –
 - USOC Jacks –
 - Hearing Aid Compatibility -
 - Repetitive Dialing to a Single Number –
 - Facility Interface Code(s)-
 - Manufacturer Port ID –
 - Service Order Codes (SOC)-
 - Answer Supervision –
 - Ancillary Equipment – (Certification Status, Trade Name, Model Number, Type, Manuf ID)

I will send the ACTA submission form, which provides an explanation and example of the items stated above.

The items indicated above must be submitted before processing can continue on the referenced application. Failure to provide the requested information within 60 days may result in application dismissal pursuant to Section 2.917(c) and forfeiture of the filing fee pursuant to Section 1.1106.

Thank you Kindly,

Monika Brandle

Do you Yahoo!?
Yahoo! Search - [Find what you're looking for faster.](#)