

INTERTEK TESTING SERVICES

hp

Report No.: C417454
Model No.: 16765

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

REF -10.0 dBm

AT 10 dB

MKR 46.500 msec


.02 dB

PEAK

LOG

10

dB/



WA SB

SC LS

CORR

Tested By: K1
(Kenneth Wong)

Date: 15/9/04

Checked By: [Signature]
([Name])

Date: 18/9/04

Test Result: Pass / Fail NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 100 msec

INTERTEK TESTING SERVICES

hp

Report No.: 0417454
Model No.: 16765


MKR 46.200 msec

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement
REF -10.0 dBm AT 10 dB

- .06 dB

PEAK
LOG
10
dB/

WA SB
SC LS
CORR



Tested By: KW
(Kenneth Wong)

Date: 15/9/04

Checked By: [Signature]
([Signature])

Date: 10/9/04

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 55.0 msec

INTERTEK TESTING SERVICES

hp

Pursuant to FCC Part 15 Section 15. ~~22~~ Emissions Requirement

MKR 1.6500 msec

Report No.: 0917454
Model No.: 16965

REF -10.0 dBm

AT 10 dB

.05 dB

PEAK

LOG


10

dB/

WA SB

SC LS

CORR



Tested By: Kenneth

Date: 15/9/04

Checked By: [Signature]
(Kenneth Chen)

Date: 18/9/04

Test Result : Pass / Fail NA

CENTER 27.145 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 55.0 msec

INTERTEK TESTING SERVICES

hp


Report No.: 0407454
Model No.: 16965

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement
REF -10.0 dBm AT 10 dB

MKR 550.00 μ sec
.07 dB

PEAK
LOG
10
dB/

WA SB
SC LS
CORR



Tested By: Ken
(Kenneth Whinn)

Date: 15/9/04

Checked By: [Signature]
(Anthony [unclear])

Date: 18/9/04

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 55.0 msec