

Helen Zhao

Subject: FW: answer: RISO KAGAKU CORPORATION, FCC ID: RPARFMHL00, Assessment NO.: AN06T6132, Notice#1



revised report.pdf



Setup
Photos(revised).pdf



Notice.pdf



Host_manual 1.pdf



Host_manual 2.pdf



Antenna and
Module Location ph..



Host Label.pdf



host photo.pdf

From: Claire Hoque

Sent: Friday, September 22, 2006 9:38 AM

To: Helen Zhao

Subject: answer: RISO KAGAKU CORPORATION, FCC ID: RPARFMHL00, Assessment NO.: AN06T6132, Notice#1

Hi Helen,

Pls see answer below, thanks.

Claire

-----Original Message-----

Sent: Wednesday, September 13, 2006 3:17 PM

Subject: RISO KAGAKU CORPORATION, FCC ID: RPARFMHL00, Assessment NO.: AN06T6132, Notice#1

Question #1: Filing does not appear to be in accordance with TCB guidance (Oct 2005 TCBC workshop notes) for modules in specific-host final-products:

BELOW HAS EXAMPLE AS LAPTOP, BUT APPLIES FOR ANY MODULE IN SPECIFIC HOST

General filing guidance for mini-PCI and similar modules, for example in notebook computer:

- Filings for specific laptop(s) need external and internal-as-installed antenna photos or drawings
- Final-product laptop approvals need laptop user manual describing wireless function, installation/operation, final-product operation, etc.
- C2pc filings to add final-product (host) should include final device FCC ID labeling info, including labels for other modules if applicable

Please provide external photos of the host printer HC5500, internal photos to show antenna location when the module is installed inside the printer, user manual of the host printer, host printer FCC ID labeling info.

<answer>Attached pls find host photo, antenna/module location photos, host manual and host label.

Endusers or Service person can not access this RF Module, therefore, host manual does not describe wireless function.

Question #2: The limits listed on the test report page 29 of 38 are incorrect. For fundamental 13.56MHz, the limit at 30m should be 15,848 uV/m (84 dBuV/m), and for harmonic 27.12MHz, the limit at 30m should be 30uV/m (29.5 dBuV/m). Please update the report.

<answer>attached pls find revised report/setup photos.

Best Regards,
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.