

Operation description

1. Plug the mouse to computer interface USB
2. Computer supplies the mouse with 5V, MCU of the mouse works and system reset. MCU works with frequency 18Mhz of Crystal oscillator.
3. Input orders to MCU via mouse, MCU starts process and sends control orders to computer