

Please find Intertek testing comments below:

1) Please clarify the FCC identifier for the Transmitter. The FCC id label exhibit is different than what is applied for. Submit the correct FCC id label as appropriate.

[RT] The label you sent me looks OK- maybe the number didn't exactly match some of your other paperwork?

(CSL) New Label printed with corrected ID number

2) Clarify the transmitter operating frequency band from the center frequency of the lowest channel to the center frequency of the highest channel. It appears that the testing was only done on one channel. Testing on channels per 15.31(m) is required. Please check with the test lab.

[RT] The operating band on FCC Form 731 should be:
2408MHz-2478MHz (to match the test report)

The reviewer did not mention the "Emission Designator" or the product "Equipment Class" - also on Form 731. Did you have any problem determining this?

The reviewer states that only (1) channel was tested on the product. This is incorrect. The report clearly has test data for (3) channels. Please ask the reviewer to take a second look.

3) Only one device can be approved under this ID. You indicated that this filing applies to the transmitter. The receiver exhibits will be deleted from this filing. Please confirm and acknowledge that the receiver will be approved separately and will not be marketed until appropriate filings(if applicable) are granted.

[RT] This is correct. The base receiver product does not have to be submitted with the radio transmitter]

Randall Thompson
Intertek