



Compliance Testing, LLC

FCC ID: RSNFLEX2GO

IC ID: N/A

CT Project: TCB-p1370007

From: John Erhard

Date: January 2, 2014

1. Please correct the final amplifier stage supply voltage and current to the block diagram to be the amplified current not the quiescent current. The maximum capable values are required.

[Cellphone-Mate - Updated Block Diagram has been provided](#)

2. The limit is still in the MSCL document with no explanation. Please explain where this limit originates or remove it from the document.

[Cellphone-Mate - Updated MSCL document has been provided](#)

Response by: Cellphone-Mate

Submitted by: Amanda Reed

Date: 1/3/2014