

I can confirm that our tests relating to RFI report 45433JD06 was tested in 3 orthogonal planes. Checks were also performed whilst all buttons were depressed in sequence to determine worse case mode of operation.

Regards

Nigel Davison Technical Service Leader (Radio)