

## **Megaforce Company Limited**

Company Address: 17F-2, 16 Jian-Ba Road, Zhong-He City,  
Taipei County, Taiwan

Tel.: +886-2-8226-5118

Fax: +886-2-8226-5116

FCC ID: RWH-MP308-00

Date: Jun. 11, 2004

Subject: Class II Change Permissive


Dear Regulatory Authority,

We, the undersigned, hereby declare, this device: MP3 FM transmitter class II change is owing to the change of:

1. U6 is optional in the circuit:  
IF USE INTERNAL RAM PUT R21 >>> means put r21 when U6 is removed  
IF USE EXTERNAL RAM PUT R22 >>> means put r22 when U6 is added
2. The channel switch located at SW4 is changed from a DP switch to a rotating one.

Please find those changes in the schematics of both old and new version.

Sincerely Yours,



24/May/2014

Jimmy Liu, R/D Senior Specialist