

U.S. Technologies, Inc.

Test Report, FCC Part 24


Report Number: 03-0321

Issue Date: December 4, 2003

Customer: Connexcel, L.L.C.

Model: Amoi A90 Cell Phone

Photo 6. Phone Receive Board – Top



U.S. Technologies, Inc.


Test Report, FCC Part 24

Report Number: 03-0321

Issue Date: December 4, 2003

Customer: Connexcel, L.L.C.
Model: Amoi A90 Cell Phone

Photo 7. Phone Receive Board – Bottom



U.S. Technologies, Inc.

Test Report, FCC Part 24


Report Number: 03-0321

Issue Date: December 4, 2003

Customer: Connexcel, L.L.C.

Model: Amoi A90 Cell Phone

Photo 8. Display Ribbon – Top



U.S. Technologies, Inc.

Test Report, FCC Part 24

Report Number: 03-0321

Issue Date: December 4, 2003

Customer: Connexcel, L.L.C.

Model: Amoi A90 Cell Phone

Photo 9. Display Ribbon – Bottom



U.S. Technologies, Inc.

Test Report, FCC Part 24


Report Number: 03-0321

Issue Date: December 4, 2003

Customer: Connexcel, L.L.C.

Model: Amoi A90 Cell Phone

Photo 10. Display – Front



U.S. Technologies, Inc.

Test Report, FCC Part 24

Report Number: 03-0321

Issue Date: December 4, 2003

Customer: Connexcel, L.L.C.

Model: Amoi A90 Cell Phone

Photo 11. Display – Back

