

MFDPPC

Differences between actual version Proto-C1 Rev2 and new version PRS2

We hereby apply for class II permissive change of FCC ID: RX2MFDPPC due to the following changes:

- 1) Daughter Board:
 - PCB review
 - Reset optimisation
 - Capacitors matching
 - Components changing
- 2) Front Panel Board:
 - PCB review
 - Components changing for brightness esthetical request
- 3) Power Board:
 - PCB review
 - Components changing
- 4) Mother Board:
 - PCB review
 - Capacitors changing (voltage level extension)
 - Components changing
 - Filters adding
 - Component optimization (BOM optimization)

All the described changes don't interest the radio part (PCB and components) of

Sincerely,

Magneti Marelli S.p.A.

