

Hello Tim,

Please be advised that updated report has just been uploaded upon your last comment, thanks!!

1. For the issue about the differences between the modular transitter itself and the device being certified by this time, I have double checked and found that the power is nearly the same as what we'd reported before. FYI, the parameter for setting the power level is "75" and that's declared by the manufacturer for the compliance testing.

2~3. Please find the updates on the report just uploaded.

Thanks!!

Eric