

Invixium Access Inc.
Address: 300-111 Gordon Baker Road Toronto M2H 3R1 Canada
Tel.: 1-416-414-0736 Fax: 1-844-468-4948
E-mail: vlazic@invixium.com

Date: 2024-12-02

FEDERAL COMMUNICATIONS COMMISSIONS
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

To Whom it May Concern,

Subject : UNII-4 Client Operation
FCC ID: S38-IXM6490

We attest the following:

1. This is a client device and it will not directly connect to another client device on any channels that are contained, even partially, within the UNII-4 band.
2. It will only associate and connect with an indoor Access Point (AP) or indoor Subordinate within the UNII-4 band.
3. It will always be under the control of an indoor AP within the UNII-4 band. It does not support active scanning in the UNII-4 bands. In the UNII-4 band if an AP is detected this client device may transmit brief messages, prior to being under the control of an AP, to join an AP network. These brief messages will have a time-out mechanism if it does not receive a response from an AP.

Should you have any questions or comments concerning the above, please contact the undersigned.

Sincerely Yours,



Contact person: Vladimir Lazic
Title: Principal Engineer