

700-3800										
DC_71A _n78A-3 700-3800	30	5+80	DFT-QPSK	M+M	Outer_Full	NV	40	7.000000	0.001867	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-QPSK	M+M	Outer_Full	NV	50	14.000000	0.003733	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+M	Outer_Full	NV	-30	4.000000	0.001067	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+M	Outer_Full	NV	-20	11.000000	0.002933	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+M	Outer_Full	NV	-10	18.000000	0.004800	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+M	Outer_Full	NV	0	15.000000	0.004000	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+M	Outer_Full	NV	10	10.000000	0.002667	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+M	Outer_Full	NV	20	16.000000	0.004267	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+M	Outer_Full	NV	30	16.000000	0.004267	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+M	Outer_Full	NV	40	2.000000	0.000533	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+M	Outer_Full	NV	50	12.000000	0.003200	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-QPSK	M+H	Outer_Full	NV	-30	1.000000	0.000266	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-QPSK	M+H	Outer_Full	NV	-20	8.000000	0.002128	PASS
DC_71A _n78A-3	30	5+80	DFT-QPSK	M+H	Outer_Full	NV	-10	2.000000	0.000532	PASS

700-3800										
DC_71A _n78A-3 700-3800	30	5+80	DFT-QPSK	M+H	Outer_Full	NV	0	9.000000	0.002394	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-QPSK	M+H	Outer_Full	NV	10	11.000000	0.002926	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-QPSK	M+H	Outer_Full	NV	20	12.000000	0.003192	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-QPSK	M+H	Outer_Full	NV	30	19.000000	0.005053	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-QPSK	M+H	Outer_Full	NV	40	12.000000	0.003192	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-QPSK	M+H	Outer_Full	NV	50	3.000000	0.000798	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+H	Outer_Full	NV	-30	4.000000	0.001064	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+H	Outer_Full	NV	-20	16.000000	0.004255	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+H	Outer_Full	NV	-10	6.000000	0.001596	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+H	Outer_Full	NV	0	18.000000	0.004787	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+H	Outer_Full	NV	10	6.000000	0.001596	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+H	Outer_Full	NV	20	11.000000	0.002926	PASS
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+H	Outer_Full	NV	30	16.000000	0.004255	PASS
DC_71A _n78A-3	30	5+80	DFT-16QAM	M+H	Outer_Full	NV	40	11.000000	0.002926	PASS

700-3800										
DC_71A _n78A-3 700-3800	30	5+80	DFT-16QAM	M+H	Outer_Full	NV	50	6.000000	0.001596	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+L	Outer_Full	NV	-30	11.000000	0.002937	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+L	Outer_Full	NV	-20	1.000000	0.000267	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+L	Outer_Full	NV	-10	4.000000	0.001068	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+L	Outer_Full	NV	0	11.000000	0.002937	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+L	Outer_Full	NV	10	9.000000	0.002403	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+L	Outer_Full	NV	20	13.000000	0.003471	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+L	Outer_Full	NV	30	11.000000	0.002937	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+L	Outer_Full	NV	40	18.000000	0.004806	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+L	Outer_Full	NV	50	2.000000	0.000534	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+L	Outer_Full	NV	-30	9.000000	0.002403	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+L	Outer_Full	NV	-20	18.000000	0.004806	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+L	Outer_Full	NV	-10	1.000000	0.000267	PASS
DC_71A _n78A-3	30	5+90	DFT-16QAM	M+L	Outer_Full	NV	0	10.000000	0.002670	PASS

700-3800										
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+L	Outer_Full	NV	10	3.000000	0.000801	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+L	Outer_Full	NV	20	18.000000	0.004806	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+L	Outer_Full	NV	30	1.000000	0.000267	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+L	Outer_Full	NV	40	8.000000	0.002136	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+L	Outer_Full	NV	50	18.000000	0.004806	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+M	Outer_Full	NV	-30	15.000000	0.004000	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+M	Outer_Full	NV	-20	17.000000	0.004533	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+M	Outer_Full	NV	-10	15.000000	0.004000	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+M	Outer_Full	NV	0	3.000000	0.000800	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+M	Outer_Full	NV	10	8.000000	0.002133	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+M	Outer_Full	NV	20	6.000000	0.001600	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+M	Outer_Full	NV	30	17.000000	0.004533	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+M	Outer_Full	NV	40	8.000000	0.002133	PASS
DC_71A _n78A-3	30	5+90	DFT-QPSK	M+M	Outer_Full	NV	50	7.000000	0.001867	PASS

700-3800										
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+M	Outer_Full	NV	-30	6.000000	0.001600	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+M	Outer_Full	NV	-20	4.000000	0.001067	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+M	Outer_Full	NV	-10	13.000000	0.003467	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+M	Outer_Full	NV	0	8.000000	0.002133	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+M	Outer_Full	NV	10	2.000000	0.000533	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+M	Outer_Full	NV	20	16.000000	0.004267	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+M	Outer_Full	NV	30	5.000000	0.001333	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+M	Outer_Full	NV	40	11.000000	0.002933	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+M	Outer_Full	NV	50	18.000000	0.004800	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+H	Outer_Full	NV	-30	11.000000	0.002929	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+H	Outer_Full	NV	-20	5.000000	0.001332	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+H	Outer_Full	NV	-10	19.000000	0.005060	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+H	Outer_Full	NV	0	9.000000	0.002397	PASS
DC_71A _n78A-3	30	5+90	DFT-QPSK	M+H	Outer_Full	NV	10	4.000000	0.001065	PASS

700-3800										
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+H	Outer_Full	NV	20	11.000000	0.002929	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+H	Outer_Full	NV	30	12.000000	0.003196	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+H	Outer_Full	NV	40	9.000000	0.002397	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-QPSK	M+H	Outer_Full	NV	50	16.000000	0.004261	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+H	Outer_Full	NV	-30	5.000000	0.001332	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+H	Outer_Full	NV	-20	16.000000	0.004261	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+H	Outer_Full	NV	-10	11.000000	0.002929	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+H	Outer_Full	NV	0	5.000000	0.001332	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+H	Outer_Full	NV	10	12.000000	0.003196	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+H	Outer_Full	NV	20	16.000000	0.004261	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+H	Outer_Full	NV	30	13.000000	0.003462	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+H	Outer_Full	NV	40	17.000000	0.004527	PASS
DC_71A _n78A-3 700-3800	30	5+90	DFT-16QAM	M+H	Outer_Full	NV	50	5.000000	0.001332	PASS
DC_71A _n78A-3	30	5+100	DFT-QPSK	M+L	Outer_Full	NV	-30	5.000000	0.001333	PASS

700-3800										
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+L	Outer_Full	NV	-20	4.000000	0.001067	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+L	Outer_Full	NV	-10	16.000000	0.004267	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+L	Outer_Full	NV	0	4.000000	0.001067	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+L	Outer_Full	NV	10	17.000000	0.004533	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+L	Outer_Full	NV	20	17.000000	0.004533	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+L	Outer_Full	NV	30	7.000000	0.001867	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+L	Outer_Full	NV	40	19.000000	0.005067	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+L	Outer_Full	NV	50	15.000000	0.004000	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+L	Outer_Full	NV	-30	15.000000	0.004000	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+L	Outer_Full	NV	-20	17.000000	0.004533	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+L	Outer_Full	NV	-10	11.000000	0.002933	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+L	Outer_Full	NV	0	13.000000	0.003467	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+L	Outer_Full	NV	10	8.000000	0.002133	PASS
DC_71A _n78A-3	30	5+100	DFT-16QAM	M+L	Outer_Full	NV	20	16.000000	0.004267	PASS

700-3800										
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+L	Outer_Full	NV	30	13.000000	0.003467	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+L	Outer_Full	NV	40	11.000000	0.002933	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+L	Outer_Full	NV	50	9.000000	0.002400	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+M	Outer_Full	NV	-30	10.000000	0.002667	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+M	Outer_Full	NV	-20	2.000000	0.000533	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+M	Outer_Full	NV	-10	4.000000	0.001067	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+M	Outer_Full	NV	0	8.000000	0.002133	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+M	Outer_Full	NV	10	9.000000	0.002400	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+M	Outer_Full	NV	20	16.000000	0.004267	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+M	Outer_Full	NV	30	11.000000	0.002933	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+M	Outer_Full	NV	40	19.000000	0.005067	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+M	Outer_Full	NV	50	2.000000	0.000533	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+M	Outer_Full	NV	-30	4.000000	0.001067	PASS
DC_71A _n78A-3	30	5+100	DFT-16QAM	M+M	Outer_Full	NV	-20	13.000000	0.003467	PASS

700-3800										
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+M	Outer_Full	NV	-10	18.000000	0.004800	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+M	Outer_Full	NV	0	12.000000	0.003200	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+M	Outer_Full	NV	10	11.000000	0.002933	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+M	Outer_Full	NV	20	2.000000	0.000533	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+M	Outer_Full	NV	30	16.000000	0.004267	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+M	Outer_Full	NV	40	1.000000	0.000267	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+M	Outer_Full	NV	50	8.000000	0.002133	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+H	Outer_Full	NV	-30	6.000000	0.001600	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+H	Outer_Full	NV	-20	1.000000	0.000267	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+H	Outer_Full	NV	-10	8.000000	0.002133	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+H	Outer_Full	NV	0	14.000000	0.003733	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+H	Outer_Full	NV	10	12.000000	0.003200	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+H	Outer_Full	NV	20	17.000000	0.004533	PASS
DC_71A _n78A-3	30	5+100	DFT-QPSK	M+H	Outer_Full	NV	30	13.000000	0.003467	PASS

700-3800										
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+H	Outer_Full	NV	40	15.000000	0.004000	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-QPSK	M+H	Outer_Full	NV	50	11.000000	0.002933	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+H	Outer_Full	NV	-30	3.000000	0.000800	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+H	Outer_Full	NV	-20	10.000000	0.002667	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+H	Outer_Full	NV	-10	11.000000	0.002933	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+H	Outer_Full	NV	0	9.000000	0.002400	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+H	Outer_Full	NV	10	12.000000	0.003200	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+H	Outer_Full	NV	20	9.000000	0.002400	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+H	Outer_Full	NV	30	18.000000	0.004800	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+H	Outer_Full	NV	40	13.000000	0.003467	PASS
DC_71A _n78A-3 700-3800	30	5+100	DFT-16QAM	M+H	Outer_Full	NV	50	11.000000	0.002933	PASS